Form 3160-5 (August 2007)

### UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB No. 1004-0137 Expires: July 31, 2010

5. Lease Serial No

6. If Indian, Allottee or Tribe Name

NMSF079192

SUNDRY NOTICES AND REPORTS ON WELLS	5
Do not use this form for proposals to drill or to re-en	nter an

abandoned well. Use Form 3160-3 (APD) for such proposals. SUBMIT IN TRIPLICATE - Other instructions on page 2. 7. If Unit of CA/Agreement, Name and/or No. 1. Type of Well Oil Well X Gas Well Other 8. Well Name and No. San Juan 28-6 Unit 123R 2. Name of Operator 9. API Well No. Hilcorp Energy Company 30-039-22265 3b. Phone No. (include area code) 3a. Address 10. Field and Pool or Exploratory Area 382 Road 3100, Aztec, NM 87410 505-599-3400 Blanco Mesaverde/Basin Dakota 4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description) 11. Country or Parish, State Surface Unit G (SWNE) 1520'FNL & 1540' FEL, Sec. 16, T28N, R06W Rio Arriba **New Mexico** 12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION X Notice of Intent Acidize Deepen Production (Start/Resume) Water Shut-Off Alter Casing Fracture Treat Reclamation Well Integrity Subsequent Report Casing Repair New Construction Recomplete Other Change Plans Plug and Abandon Temporarily Abandon Convert to Injection Final Abandonment Notice Plug Back Water Disposal 13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once Testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.) Hilcorp Energy Company plans to recomplete the subject well in the Mesaverde formation and downhole commingle with the existing Dakota. Attached is the MV C102, recomplete procedure & wellbore schematic. The DHC application will be submitted and approved prior to commingling. A closed loop system will be utilized. Interim reclamation will be HOLD C104 FOR Density exception performed after surface disturbing activities. BLM'S APPROVAL OR ACCEPTANCE OF THIS ACTION DOES NOT RELIEVE THE LESSEE AND OPERATOR FROM OBTAINING ANY OTHER **AUTHORIZATION REQUIRED FOR OPERATIONS** ON FEDERAL AND INDIAN LANDS SUBMIT CBL TO THE AGENCIES FOR REVIEW AND 14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed) APPROVAL Tammy Jones Operations/Regulatory Technician - Sr. 11/27/2018 Signature Date THIS SPACE FOR FEDERAL OR STATE OFFICE USE Approved by Conditions of approval of any, are attached. Approval of this notice does not warrant or certify

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

entitle the applicant to conduct operations thereon

that the applicant holds legal or equitable litle to those rights in the subject lease which would

District I

1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720

District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170 **District IV** 

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

## State of New Mexico **Energy, Minerals and Natural** Resources

Oil Conservation Division 1220 S. St Francis Dr. Santa Fe. NM 87505

### WELL LOCATION AND ACREAGE DEDICATION PLAT

1. API Number 30-039-22265	2. Pool Code 72319	3. Pool Name BLANCO-MESAVERDE (PRORATED GAS)
4. Property Code	5. Property Name	6. Well No.
318710	SAN JUAN 28 6 UNIT	123R
7. OGRID No.	8. Operator Name	9. Elevation
372171	HILCORP ENERGY COMPANY	6699


#### 10. Surface Location

UL - Lot		Section		Township		Range		Lot Idn	Feet From	N/S Line	Feet From	E/W Line	County	
	G		16		28N		06W		1520	N	1540	E	R	IO ARRIBA

#### 11. Bottom Hole Location If Different From Surface

UL - Lot	Section	Township	Range	Lot Idn	Feet From	N/S Line	Feet From	E/W Line	County
12. Dedicated Acres 320.00			13. Joint or Infill		14. Consolidation	on Code	15. Order No.		

#### NO ALLOWABLE WILL BE ASSIGNED TO THIS COMPLETION UNTIL ALL INTERESTS HAVE BEEN CONSOLIDATED OR A NON-STANDARD UNIT HAS BEEN APPROVED BY THE DIVISION



#### **OPERATOR CERTIFICATION**

Form C-102

August 1, 2011

Permit 260262

I hereby certify that the information contained herein is true and complete to the best of my knowledge and belief, and that this organization either owns a working interest or unleased mineral interest in the land including the proposed bottom hole location(s) or has a right to drill this well at this location pursuant to a contract with an owner of such a mineral or working interest, or to a voluntary pooling agreement or a compulsory pooling order heretofore entered by the division.

E-Signed By: Tammy Jones

Title:

Operations/Regulatory Technician - Sr.

Date:

11/27/2018

#### SURVEYOR CERTIFICATION

I hereby certify that the well location shown on this plat was plotted from field notes of actual surveys made by me or under my supervision, and that the same is true and correct to the best of my belief.

Surveyed By:

Fred B. Kerr Jr.

Date of Survey:

8/3/1979

Certificate Number:

3950



# HILCORP ENERGY COMPANY San Juan 28-6 Unit 123R MESA VERDE RECOMPLETION SUNDRY

#### JOB PROCEDURES

- 1. MIRU service rig and associated equipment; test BOP.
- 2. TOOH with 2 3/8" tubing set at 7,941'.
- 3. Set a 4-1/2" cast iron bridge plug at +/- 6,240' to isolate the Dakota.
- 4. Load the hole run a CBL from the CIBP to Surface.
- 5. Pressure test the casing.
- 6. N/D BOP, N/U frac stack and test frac stack to frac pressure.
- 7. Perforate and frac the Mesa Verde (Top Perforation @ 5,230'; Bottom Perforation @ 6,195').
- 8. Nipple down frac stack, nipple up BOP and test.
- 9. TIH with a mill and drill out top isolation plug and Mesa Verde frac plugs.
- 10. Clean out to Dakota isolation plug.
- 11. Drill out Dakota isolation plug and cleanout to PBTD of 8,034'. TOOH.
- 12. TIH and land production tubing.



# HILCORP ENERGY COMPANY San Juan 28-6 Unit 123R MESA VERDE RECOMPLETION SUNDRY

