State of New Mexico Energy, Minerals and Natural Resources Department

Michelle Lujan Grisham Governor Sarah Cottrell Propst Adrienne Sandoval, Division Director Cabinet Secretary Oil Conservation Division Todd E. Leahv. JD. PhD **Deputy Secretary** New Mexico Oil Conservation Division approval and conditions listed below are made in accordance with OCD Rule 19.15.7.11 and are in addition to the actions approved by BLM on the following 3160-4 or 3160-5 form. Operator Signature Date: 2/20/2019 Well information: HILCORP ENERGY COMPANY 30-039-20267 Carson SRC #1 Application Type: Drilling/Casing Change Location Change P&A Recomplete/DHC (For hydraulic fracturing operations review EPA Underground injection control Guidance #84; Submit Gas Capture Plan form prior to spudding or initiating recompletion operations) Other: Conditions of Approval: Notify the OCD 24hrs prior to beginning operations. Hold the C-104 for the DHC. The initial CIBP must be placed no higher than 50' above the existing perforations. Submit the CBL to the agencies for review and approval prior to perforating. A Mechanical integrity test (MIT) must be performed from the initial CIBP to verify the integrity of the well. The pressure test must meet the requirements of 19.15.25.14 NMAC. 24hr notice is required to be provided to the agencies prior to performing the MIT. After the MIT is performed a second temporary isolating device may be set up near the requested recomplete interval without additional OCD approval to protect the casing from the completion pressures. If needed, submit a proposed remediation plan to the agencies for review and approval prior to starting remediation. 4/22/19

Date

NMOCD Approved by Signature

Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB No. 1004-0137

Expires: July 31, 2010

5. Lease Serial No.

NMNM4453

SUNDRY NUTICES AND REPORTS ON WELLS	1
Do not use this form for proposals to drill or to re-enter an	
abandoned well. Use Form 3160-3 (APD) for such proposals	

6. If Indian, Allottee or Tribe National Of 7. If Unit of CA/Agreement, Name and/or No. SUBMIT IN TRIPLICATE - Other instructions on page 2. 1. Type of Well Oil Well X Gas Well 8. Well Name and No. Other Carson SRC 1 2. Name of Operator 9. API Well No. Hilcorp Energy Company 30-039-20267 3a. Address 3b. Phone No. (include area code) 10. Field and Pool or Exploratory Area 505-599-3400 East Blanco Pictured Cliffs/Blanco MV 382 Road 3100, Aztec, NM 87410 4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description) 11. Country or Parish, State Surface Unit L (NWSW) 1540' FSL & 990' FWL, Sec. 1, T30N, R05W Rio Arriba New Mexico 12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Notice of Intent Acidize Deepen Production (Start/Resume) Water Shut-Off Well Integrity Alter Casing Fracture Treat Reclamation Subsequent Report Casing Repair New Construction Recomplete Other

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once Testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

Plug Back

Plug and Abandon

Hilcorp Energy Company plans to recomplete the subject well in the Pictured Cliffs formation and downhole commingle with the existing Mesaverde. Attached is the PC C102, recomplete procedure & wellbore schematic. The DHC application will be submitted and approved prior to commingling. A closed loop system will be utilized. Interim reclamation will be performed after surface disturbing activities.

HOLD C104 FOR DAC

Change Plans

Convert to Injection

Final Abandonment Notice



Temporarily Abandon

Water Disposal

14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed)				
Tammy Jones	Title	Operations/I	Regulatory Technician -	Sr.
Signature Tammy Janos	Date		2/20/201	19
THIS SPACE FOR FEI	DERAL O	R STATE OF	FICE USE	
Approved by SM andielor		Title	AFM	Date 3/13/19
Conditions of approval, if any, are attached. Approval of this notice does not warrant	or certify			
that the applicant holds legal or equitable title to those rights in the subject lease whice entitle the applicant to conduct operations thereon.	ch would	Office	FFO	

false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.



District I

1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720

District II

811 S. First St., Artesia, NM 88210 Phone: (575) 748-1283 Fax: (575) 748-9720 **District III**

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170 **District IV**

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone: (505) 476-3470 Fax: (505) 476-3462

State of New Mexico **Energy, Minerals and Natural** Resources **Oil Conservation Division** 1220 S. St Francis Dr.

Form C-102 August 1, 2011

Permit 263985

WELL LOCATION AND ACREAGE DEDICATION PLAT

Santa Fe, NM 87505

1. API Number	2. Pool Code	3. Pool Name
30-039-20267	72400	BLANCO PICTURED CLIFFS, EAST (GAS)
4. Property Code	5. Property Name	6. Well No.
318473	CARSON SRC	001
7. OGRID No.	8. Operator Name	9. Elevation
372171	HILCORP ENERGY COMPANY	6590


10. Surface Location

										_
UL - Lot	Section	Township	Range	Lot Idn	Feet From	N/S Line	Feet From	E/W Line	County	l
L	1	30N	05W		1540	S	990	W	RIO ARRIBA	
				į l				1		ı

11. Bottom Hole Location If Different From Surface

IN DOUBLE TO BOTH TO B										
UL - Lot	ot Section Township		Range Lot Idn		Feet From	N/S Line	N/S Line Feet From		County	
	<u> </u>									
12. Dedicated Acres		13. Joint or Infill		14. Consolidation Code			15. Order No.			
l 319.29 l										

NO ALLOWABLE WILL BE ASSIGNED TO THIS COMPLETION UNTIL ALL INTERESTS HAVE BEEN CONSOLIDATED OR A NON-STANDARD UNIT HAS BEEN APPROVED BY THE DIVISION



OPERATOR CERTIFICATION

I hereby certify that the information contained herein is true and complete to the best of my knowledge and belief, and that this organization either owns a working interest or unleased mineral interest in the land including the proposed bottom hole location(s) or has a right to drill this well at this location pursuant to a contract with an owner of such a mineral or working interest, or to a voluntary pooling agreement or a compulsory pooling order heretofore entered by the division.

Tammy Jones E-Signed By:

Title:

Operations/Regulatory Technician - Sr.

Date:

2/20/2019

SURVEYOR CERTIFICATION

I hereby certify that the well location shown on this plat was plotted from field notes of actual surveys made by me or under my supervision, and that the same is true and correct to the best of my belief.

Surveyed By:

Fred B. Kerr Jr.

Date of Survey:

6/19/1969

Certificate Number:

3950



HILCORP ENERGY COMPANY CARSON SRC 1 PICTURED CLIFFS RECOMPLETION SUNDRY

JOB PROCEDURES 1995

- 1. MIRU service rig and associated equipment; test BOP.
- 2. TOOH with 2-3/8" tubing set at 8,050'.
- 3. Set a 4-1/2" plug at +/- 4,000' to isolate the Mesaverde formation and Dakota formation.
- 4. RU Wireline. Run CBL and record Top Cement,
- 5. IF NECESSARY (Based on the results of the CBL top of cement) Perform squeeze work.
- 6. Load the hole and pressure test the casing.
- 7. N/D BOP, N/U frac stack and pressure test frac stack.
- 8. Perforate and frac the Pictured Cliffs formation (Top Perforation @ 3,377; Bottom Perforation @ 3,680').
- 9. Isolate frac stage with a plug.
- 10. Nipple down frac stack, nipple up BOP and test.
- 11. TIH with a mill and drill out top Pictured Cliffs isolation plug.
- 12. Clean out to Mesaverde formation and Dakota formation isolation plug.
- 13. Drill out Mesaverde formation and Dakota formation isolation plug and cleanout to PBTD of 8,200°. TOOH.
- 14. TIH and land production tubing. Get a trimingled Dakota/Mesaverde/Pictured Cliffs flow rate.



Current Schematic - Version 3

Well Name: CARSON SRC #1

