	Form 3160-5 (June 2015) UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS					FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018 5. Lease Serial No. NMSF080647	
					5		
	Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.				(6. If Indian, Allottee or Tribe Name	
=	SUBMIT IN TRIPLICATE - Other instructions on page 2				5	7. If Unit or CA/Agreement, Name and/or No.	
-	1. Type of Well □ Oil Well ⊠ Gas Well □ Other				8. Well Name and No. GALLEGOS CANYON UNIT 533		
_	2. Name of Operator Contact: PATTI CAM BP AMERICA PRODUCTION COMPA® Mail: patti.campbell@bpx.com					9. API Well No. 30-045-28733	
_	3a. Address 380 AIRPORT ROAD DURANGO, CO 81303		3b. Phone No. (include area code) Ph: 970-712-5997		1	10. Field and Pool or Exploratory Area BLANCO PICTURED CLIFFS	
- - -	4. Location of Well (Footage, Sec., T., R., M., or Survey Description)					11. County or Parish, State	
	Sec 22 T29N R12W Mer NMP NWSW 1760FSL 1170FWL					SAN JUAN CO	UNTY COUNTY, NM
	12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE					EPORT, OR OT	HER DATA
	TYPE OF SUBMISSION		TYPE OF ACTION				
	Notice of Intent	Acidize		Deepen		n (Start/Resume)	□ Water Shut-Off
2	Subsequent Report	 Alter Casing Casing Repair 	Hydraulic Fracturing New Construction		 Reclamation Recomplete 		□ Well Integrity □ Other
	□ Final Abandonment Notice			g and Abandon	Temporar		- Other
	5	Convert to Injection				'ater Disposal	
	Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.						
-	BP has determined the subject well has a recomplete potential in the Fruitland Coal for requests approval to Temporarily Abandon (TA) the subject well.						
	Please see the attached procedure including wellbore diagrams.					APR	0 1 2019
	In accordance with NMOCD Pit Rule 19.15.17.9 NMAC, BP will use a close operations.				stem during	DISTR	ICT 111
			ACTION DOE OPERATOR H AUTHORIZA	ROM OBTAININ	THE LESSEE AND G ANY OTHER FOR OPERATIONS		
	14. Thereby certify that the foregoing is true and correct. Electronic Submission #456757 verified by the BLM Well Information System For BP AMERICA PRODUCTION COMPANY, sent to the Farmington Committed to AFMSS for processing by MARJORIE BROWN on 03/21/2019 ()						\
	Name (Printed Typed) PATTI CAMPBELL			Title REGUL	ATORY ANA	LYST	
	Signature (Electronic Submission)			Date 03/04/2			
	THIS SPACE FOR FEDERAL OR STATE OFFICE USE						
(_Approved ByConditions of approved, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease			Title CE			Date 3 21
:	which would entitle the applicant to conduct operations thereon. Office FFO Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.						r agency of the United
	(Instructions on page 2)						

NMOCDA

----BP-America

Plug And Abandonment Procedure

GCU 533

1760' FSL & 1170' FWL, Section 22, T29N, R12W

San Juan County, NM / API 30-045-28733

1. Hold pre-job safety meeting. Comply with all NMOCD, BLM safety and environmental regulations. Test rig anchors prior to moving in rig if not rigged to base beam.

2. Check casing, tubing, and Bradenhead pressures.

3. Remove existing piping on casing valve. RU blow lines from casing valves and begin blowing down casing pressure. Kill well as necessary. Ensure well is dead or on a vacuum.

4. ND wellhead and NU BOP. Function test BOP.

- 5. P/U 4-1/2" bit or casing scraper on 2-3/8" workstring and round trip as deep as possible above top perforation at 1537'.
- 6. P/U 4-1/2" CIBP, RIH and set CIBP at +/- 1487'. Pressure test tubing to 1000 psi. Load hole, and perform MIT test to 560 psi for 2 hours. If casing passes MIT test well can be shut-in and given a T&A designation once sundry has been submitted upon completion of work.
- 7. L/D workstring. N/D BOP, N/U wellhead and shut-in well. R/D and MOL.



Wellbore Diagram

a. . . .

Gallegos Canyon Unit 533 API #: 3004528733 San Juan County, New Mexico

