Form 3160- 5 (April 2004)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

Š		
	Ć	1
RCUD	S	

Recomplete

Water Disposal

remporarily Abandon

FORM APPROVED

OMB No. 1004- 0137 Expires: March 31, 2007

SUNDRY NOTICES	AND REPORTS ON WELLS	,
Do not use this form for	proposals to drill or to re-enter âi	$\eta \cap \gamma$

Contract 451

6. If Indian, Allottee, or Tribe Name

abandoned well. Use Form 3160-3 (APD) for such proposals.			Jicarilla Apache Tribe	
SUBMIT IN TRIPLICATE - Other Instructions on reverse side.		7. If Unit or CA. Agreement Name and/or No.		
1. Type of Well		ye mail a common of the common	To provide the state of the sta	
Oil Well X Gas Well Other		8. Well Name and No.		
2. Name of Operator		Jicarilla 451-03 #14		
Black Hills Gas Resources, Inc.		9. API Well No.		
3a. Address		3b. Phone No. (include area code)	30-039-29266	
P.O. Box 249 Bloomfield, NM 87413 505-634-1111		10. Field and Pool, or Exploratory Area		
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)		East Blanco, PC; Cabresto Can, Tertiary		
Sec 03, T29N, R03W 740' FNL & 610' FEL Unit A		11. County or Parish, State		
			Rio Arriba, NM	
12. CHECK APPROI	PRIATE BOX(S) TO INDICA	TE NATURE OF NOTICE, REPO	ORT, OR OTHER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION			
X Notice of Intent	Acidize	Deepen Production	(Start/ Resume) Water Shut-off	
	Altering Casing	Fracture Treat Reclamation	n Well Integrity	

'13. Describe Proposed or Completed Operation (clearly state all pertinent details including estimated starting date of any proposed work and approximate duration thereof.

If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths or pertinent markers and sands.

Attach the Bond under which the work will performed or provide the Bond No. on file with the BLM/ BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notice shall be filed only after all requirements, including reclamantion, have been completed, and the operator has determined that the site is ready for final inspection.)

Convert to Injection

Black Hills Gas Resources intends to plug back and abandon the Pictured Cliffs, Fruitland Coal and Lower Nacimiento formations in this well as per attached procedure. The remaining Tertiary will be evaluated to determine the best production configuration.

SEE ATTACHED FOR CONDITIONS OF APPROVAL

14. I hereby certify that the foregoing is true and correct.				
Name (Printed/ Typed)	and a			
Loren Diede	Title Consultant (Agent)			
Signature Signature	Date Oct 24, 2006			
THIS-SPACE FOR FEDERAL OR STATE OFFICE USE				
Approved by Majore wounder	Title Pet. Eng, Date 10/31/06			
Conditions of approval of any are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease Office which would entitle the applicant to conduct operations thereon.				
Title 18 U.S.C. Section 1001 AND Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.				

(Instructions on page 2)

Black Hills Gas Resources

Workover Procedure For the

JICARILLA 451-03 #14

API # 30-039-26266 SW NE Sec 3, T 29N, R 3W Rio Arriba County, New Mexico

GL=7246', KB=7259', TD=3857', PBTD= 3835'

Surface casing:

ŧ

8-5/8", 24 lb/ft, @ 284', TOC = surf

Production casing:

5 ½" 15.5lb/ft, K-55 @ 3847' TOC=Surf

Production Tubing:

110 Jts 2 3/8" 4.7# J-55 @ 3591'w/ packer & 4 jts tail pipe

Current Perforations:

 Upper San Jose
 1352-1400

 Lower San Jose/Nac
 1676-2140

 L Nacimiento
 3150-3190

 Fruitland Coal
 3638-3694

 Pictured Cliffs
 3732-3814

Proposed Work: Abandon the PC & FC, evaluate the Tertiary.

General Note: All fluids entering the well bore are to contain; 2 gpt MA-844 (MA-1), 2% KCl and a biocide.

Notify the Jicarilla BLM to witness the plug back at least 24 hr prior to pumping the cement.

Plug Back

- 1. Conduct safety meeting with all personnel to discuss the scope of this completion.
- 2. MIRU completion rig, ND WH, NU BOP.
- 3. Unset the packer and TOOH with production tubing. Visually inspect tubing for scale and corrosion.
- 4. TIH with bit and scraper to at least 3710'. TOOH.
- 5. TIH with CIBP and set @ +/- 3705'. Pull off the CIBP and pump 44 cu ft (33 sx) Type V cement to cover the Fruitland Coal and Kirtland formation tops.
- 6. Pull up well above the cement, (at least 10 stands). WOC
- 7. Trip down and tag TOC. TOC is to be at least 3388' or higher. If needed, top off to achieve a TOC of 3388'. TOOH.

- 8. Pull up to 3318' and pump a balanced cement plug of 33 cu ft (25 sx) Type V cement from 3318' to 3100' to cover the Ojo Alamo formation top and Lower Nacimiento perforations. WOC.
- 9. Trip down and tag TOC. TOC is to be at least 3100' or higher. If needed, top off to achieve a TOC of 3100'. TOOH.

Type III cement @ 14.5 ppg = 1.39 cu ft/sx Type V cement @ 14.8 ppg = 1.32 cu ft/sx Class B cement @ 15.6 ppg = 1.18 cu ft/sx

Tertiary Evaluation

- 10. TIH with tubing with EOT @ \pm 2500'.
- 11. Run a check in the tubing and pump-simulate by pulling fluid from the tubing while flowing and measuring gas from the casing. Hold a minimum of 40 psi on the casing while pump-simulating. Report pressures and rates to engineering.

The results of the pump-simulation will determine the artificial lift design.

Initiated by:

Loren Diede, 10-24-06

Approved by: Leslie Lam

JICARLLA EMERGENCY NUMBERS

Hospital/Ambulan	ce 911
Helicopter	505 334-6622
Fire/ Rescue	505 759-3254
Non	Emergency 505 334-6622
Sheriff (San Juan	505-334-6622
State Police	505 325-7547
Jicarilla PD	505 759-3222
Non	Emergency 505 334-6622


Jicarilla 451-03 #14

Post Completion Wellbore Diagram

API # 30-039-29266

UNIT A NE/NE, Sec 03, T29N, R03W Rio Arriba, NM

Elev. GL= 7246' Elev. KB= 7259'



Prepared: 22-Sep-06


Jicarilla 451-03 #14

Plug Back Wellbore Diagram

API # 30-039-29266

UNIT A NE/NE, Sec 03, T29N, R03W Rio Arriba, NM

Elev. GL= 7246' Elev. KB= 7259'



Prepared: 24-Oct-06

BLM CONDITIONS OF APPROVAL

WORKOVER AND RECOMPLETION OPERATIONS:

A properly functioning BOP and related equipment must be installed prior to commencing workover and/or recompletion operations.

SURFACE USE OPERATIONS:

The following Stipulations will apply to this well unless a particular Surface Managing Agency or private surface owner has supplied to BLM and operator a contradictory environmental stipulation. The failure of operator to comply with these requirements may result in assessments or penalties pursuant to 43 CFR 3163.1 or 3163.2. A copy of these conditions of approval shall be present on location during construction, drilling and reclamation activity.

An agreement between operator and fee landowner will take precedence over BLM surface stipulations unless (in reference to 43 CFR Part 3160) 1) BLM determines that operator's actions will affect adjacent Federal or Indian surface, or 2) operator does not maintain well area and lease premises in a workmanlike manner with due regard for safety, conservation and appearance, or 3) no such agreement exists, or 4) in the event of well abandonment, minimal Federal restoration requirements will be required.

STANDARD STIPULATIONS: All surface areas disturbed during work-over activities and not in use for production activities will be reseeded. This should occur in the first 90 days after completion of work-over activities.

SPECIAL STIPULATIONS:

- 1. Pits will be fenced during work-over operation.
- 2. All disturbance will be kept on existing pad.
- 3. All pits will be pulled and closed immediately upon completion of the work-over activities.
- 4. Pits will be lined with an impervious material at least 12 mils thick.