

CURRENT WELLBORE

5-14-2007

Tapp LS #3

Sec 15, T28N, R8W

API # 30-045-07425

GR: 5839'

History:

Completed as MV/PC dual in Mar 1958

July 1996: Performed bradenhead repair, Menefee payadd, and downhole commingled.

Pictured Cliffs Perforation

2316' - 2406' w/ 40,000 # sand

2 3/8" EOT @ 3200'
4.7" J55

Mesaverde Perforations

CH: 3982' - 4022' w/ 40,000# sand (sqz'd w/ 100 sxs cmt)

CH/MF (1996 payadd): 3944' - 4408' frac'd w/ 64,000# sand

PL: 4498' - 4650' w/ 60,000# sand

NOTES:

est. TOC @ surface (circ)

10-3/4" 32.75# SW @ 172'
150 sxs cmt (circulated)

sqz holes @ 1040'
circulated to surface

Est. TOC @ 1370' (1996 CBL)

Production
PALMER @ 2560

5-1/2" liner hanger @ 2425'

7-5/8" 26.4#, J55 @ 2475'
150 sxs cmt

Est. TOC @ 2930' (temp sury)

TOC @ 2810' - 2007 CBL

3256' - SP1 CHACRA

3276

3300

3315

3378

3418

3435

3450

360 HOLES

Composite Drilling BPO 3600

Tubing: 2-3/8" 4.7#, J55 Rrd @ 4450'

5-1/2" liner, 15.5#, J55 @ 4716'
250 sxs cmt

PBTD: 4659'

TD: 4721'

updated: 11/28/06 JG