	BUREAU O	F CAND MANAGEMENT	PECEIVE	D	
	Sundry Noti	ces and Reports o	n Wells		
		70	3 SEP 29 M	1:215.	Lease Number I149IND8468
1. <b>T</b>	ype of Well GAS	07	() Famington,	, <sub>NM</sub> 6.	If Indian, All. or Tribe Name Eastern Navajo
2 N	ame of Operator			7.	Unit Agreement Name
	BURLINGTON	GAS COMPANY	\$ 00 A		
	ddress & Phone No. of Operat PO Box 4289, Farmington, NM	87499 (505) 326-	9700	8. 9.	Well Name & Number Navajo B 6M API Well No. 30-045-23638
	ocation of Well, Footage, Se 190'FNL,790'FWL, Sec.19, T-2		Penny.	ුු ්ර Blan	Field and Pool  co MV/Basin DK/Otero Ci  County and State San Juan Co, NM
	CHECK APPROPRIATE BOX TO IND			RT, OTHER	DATA
T	ype of Submission _X_ Notice of Intent	Abandonment		nge of Pla	
]	Subsequent Report	_XRecompletion		V Construc	tion Tracturing
-	bubbedaene nepere	Plugging Bac			
7.2	Final Abandonment	Casing Reparation Case Other	ir Wate	er Shut of	
It is in will be will be a sing	<del></del>	Casing Repairable Casing Casin	REVISED The existing for nulated. The we	er Shut of version to mations	f
It is in will be will be a sing The C	Final Abandonment  Describe Proposed or Completended to add the Chacra formation to a isolated and the Chacra interval perfectle cleaned out to plug back total depth. The string of tubing. A down hole complete cleaned out to plug back total depth.	Casing Repairable Casing Repairable Casing C	REVISED The existing for nulated. The we not be commingled a submitted.  OH. Load hole s	mations il using	ff Injection
will be will be a sing The C MIRU MU a	Pinal Abandonment  Describe Proposed or Completended to add the Chacra formation to established and the Chacra interval perfect cleaned out to plug back total depth. gle string of tubing. A down hole compliff House interval will be squeezed as wireline, MU 5-1/2" CIBP & RIH and string the complete c	Casing Repairable Casing Casin	REVISED The existing for nulated. The we have commingled e submitted.  OH. Load hole serviced field TOC at 1133	mations llbore d using lowly to eliminary.	inate trapped air.
It is in will be will be a sing The C	Final Abandonment  Describe Proposed or Completended to add the Chacra formation to elisolated and the Chacra interval perfectle cleaned out to plug back total depth. gle string of tubing. A down hole complete the complete string of tubing. A down hole complete string of tubing the string of tubing of the string of the stri	Casing Repairable Altering Casing Cas	REVISED The existing for nulated. The we not be commingled to submitted.  OH. Load hole submitted to the total to the tota	mations llbore d using lowly to eliminary.	inate trapped air.
It is in will be will be a sing. The Common MIRU MU a RU will a RU will be a sing. The Common MIRU MU a RU will be a sing. The Common MIRU will be a sing. The	Pinal Abandonment  Describe Proposed or Completended to add the Chacra formation to e isolated and the Chacra interval perfectly cleaned out to plug back total depth. It is string of tubing. A down hole complete string of tubing. A light and selection of the string of tubing of the string of t	Casing Repairable Altering Casing Repairable Altering Casing Altering Casing Altering Casing Aller All	REVISED The existing for nulated. The we not be commingled as submitted.  OH. Load hole segret field TOC at 113 and 2200'. RD at 3610'.	mations libore lusing lowly to elimi 7'). re perforate wireline com and backside nting compai	inate trapped air.  5 ½" casing with 1 SPF, 0.32" apany.  with 2% KCl. Pump 450 sxs by
It is in will be will be a sing. The Common MIRU MU a RU will amount of the Common MIRU MU a RU will amount of the Common MIRU will be a single will be	Pinal Abandonment  Describe Proposed or Completended to add the Chacra formation to escape and the Chacra interval perfect cleaned out to plug back total depth. It is string of tubing. A down hole complete string interval will be squeezed as wireline, MU 5-1/2" CIBP & RIH and some RIH with GR/CCL/CBL and log from the string company. Under lubricator, RIF eter, 14.3" penetration, 10 gram charge the string company and establish establish excess) neat cement down tubing and	Casing Repairable Altering Casing Repairable Altering Casing Altering Casing Altering Casing the existing wellbore. The existing wellbore and fracture stire All formations will the iningle application will be follows:  Set CIBP at 3700'. POWA 3700' to 1000' (unversity with 3-1/8" HSC casing sets (Owen, 302) at 3660 tubing to set retainer a colish circulation through the circulate around back	REVISED The existing for nulated. The we had be commingled as submitted.  OH. Load hole segretary field TOC at 113 and 2200'. RD and 2200'. RD at tubing and arous side. RD cemeic CONDITIONS	mations libore lusing lowly to elimi 7'). re perforate wireline com and backside nting compai	inate trapped air.  5 ½" casing with 1 SPF, 0.32" apany.  with 2% KCl. Pump 450 sxs by
It is in will be will be a sing. The Common MIRU MU a RU will be a sing. The Common MIRU MU a RU will be a sing. The Common MIRU a sing. The Common MIRU will be a sing. The Common MIRU will	Pescribe Proposed or Complatended to add the Chacra formation to escape and the Chacra interval perfect cleaned out to plug back total depth. Ble string of tubing. A down hole complified the squeezed as wireline, MU 5-1/2" CIBP & RIH and so and RIH with GR/CCL/CBL and log from the string company. Under lubricator, RIP eter, 14.3" penetration, 10 gram charge the string company and establish establish excess) neat cement down tubing and the string company and establish establish excess) neat cement down tubing and the string company and establish establish excess.	Casing Repairable Altering Casing Repairable Altering Casing Altering Casing Altering Casing the existing wellbore. The existing wellbore and fracture stire All formations will the iningle application will be follows:  Set CIBP at 3700'. POWA 3700' to 1000' (unversity with 3-1/8" HSC casing sets (Owen, 302) at 3660 tubing to set retainer a colish circulation through the circulate around back	REVISED The existing for nulated. The we be commingled e submitted.  OH. Load hole s fied TOC at 113 and 2200'. RD t 3610' and tubing and around side. RD cemer CONDITIONS Adhere to previous	mations libore lusing lowly to elimi 7'). re perforate wireline com and backside nting compai	inate trapped air.  5 ½" casing with 1 SPF, 0.32" apany.  with 2% KCI. Pump 450 sxs any  DVAL dations.

Sting out of retainer and POOH. WOC

PU 4 3/4" bit and TIH on 2 3/8" tubing. Tag cement retainer at 3610' and drill out retainer and cement. TIH to tag CIBP at 3700'. TOOH

RU stimulation company. Pressure test surface lines to 4000 psi for 5 minutes, pressure test casing to 3000-psi for 15 minutes. If the pressure test fails begin leak isolation, a cement squeeze procedure will be forth coming from the engineer. If the casing pressure test holds continue with Chacra recompletion