*			4.				
In Lieu of Form 3160 (June 1990)		DEPARTMENT	UNITED STATES DEPARTMENT OF INTERIOR BUREAU OF LAND MANAGEMENT		NED 9 2 <del>003</del>	FORM APPROVED Budget Bureau No 1004-0135 Expires: March 31, 1993	
Do not i		SUNDRY NOTICE AND RE posals to drill or to deepen or ree TO DRILL" for permit for	ntry to a different reservoir	Bureau of Land Use Applicatio Farmington F	Mahagement Nelc Office 6.	Lease Designation and Serial No Jicarilla Apache Contract #93 If Indian, Allottee or Tribe Name Jicarilla Apache Nation	
<u>,                                     </u>	· ·	SUBMIT IN TRIP	LICATE		7.	If Unit or CA, Agreement Designation	
1	Type of Well Oil Well Gas W	ell X Other		-	8.	Well Name and No Jicarilla 93 #12B	
2.	Name of Operator				9.	API Well No.	

	WILLIAMS PRODUCTION COMPANY		30-039-29805
3.	Address and Telephone No. PO BOX 640 Aztec, NM 87410-0640	10.	Field and Pool, or Exploratory Area Blanco MV
4.	Location of Well (Footage, Sec., T, R, M, or Survey Description) 1190' FNL & 660' FWL, Sec. 34, T27N, R3W	11.	County or Parish, State Rio Arriba, NM

	CHECK APPROPRI	ATE BOX(s) TO INDICATE NATURE OF NOTIC	CE, REPORT, OR C	DTHER DATA
	TYPE OF SUBMISSION		TYPE OF ACTION	٧
11	X Notice of Intent	Abandonment	х	Change of Plans
Y .		Recompletion		New Construction
<i>[</i>	Subsequent Report	Plugging Back		Non-Routine Fracturing
		Casing Repair		Water Shut-Off
	Final Abandonment	Altering Casing		Conversion to Injection
		Other		Dispose Water
				(Note: Report results of multiple completion on
				Well Completion or Recompletion Report and
				Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertunent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Due to a change in plans, Williams Production Company, LLC. would like to change it's casing and cementing plans as per attached operations plan.

> RCVD NOV 25 '08 OIL CONS. DIV.

# **CONDITIONS OF APPROVAL**

Adhere to previously issued stipulations.

DIST. 3

14. I hereby certify that the foregoing is true and correct Signed Title Drilling COM Date 11-19-2008 Larry Higgins (This space for Federal or State office use) Date 11/25/08 Pet. Eng. Title Approved by Conditions of approval, if any

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction 17/1

В

NINNU





NOV 24 2008

# WILLIAMS PRODUCTION COMPANY

Eureau of Lune finant comon? Farmington Field Cince

)

# **Operations** Plan

(Note: This procedure will be adjusted on site based upon actual conditions)

DATE:	11/13/2008	FIELD:	Blanco MV
WELL NAME:	Jicarilla 93 #12B	SURFACE:	BOIA
BH LOCATION:	NWNW Sec 34-27N-3W Rio Arriba, NM	MINERALS:	Jicarilla #93
ELEVATION:	7,181' GR	LEASE #	Jıcarilla #93

MEASURED DEPTH: 6,530'

I. <u>GEOLOGY:</u> Surface formation - San Jose

## A. FORMATION TOPS: (KB)

Name	MD	Name	MD
Ojo Alamo	3,520	Cliff House	5,635
Kirtland	3,635	Menefee	5,785
Fruitland	3,695	Point Lookout	6,100
Picture Cliffs	3,895	Mancos	6,340
Lewis	4,095	TD	6,530
Huerfanito Bentonite	4,425		<i>'</i>

## B. MUD LOGGING PROGRAM: None

- C. <u>LOGGING PROGRAM</u>: High Resolution Induction log from surface shoe to TD. GR and Density/ Neutron log over zones of interest. Onsite geologist will pick Density/ Neutron log intervals on logging runs.
- **D.** <u>NATURAL GAUGES:</u> Gauge any noticeable increases in gas flow. Record all gauges in Tour book and on morning reports.

# II. DRILLING

- A. <u>MUD PROGRAM</u>: Clear water with benex to 7-5/8" casing point. Convert to a LSND mud to log and run pipe. Treat for lost circulation as necessary. Obtain 100% returns prior to cementing. Notify Engineering of any mud losses.
- B. <u>BOP TESTING:</u> While drill pipe is in use, the pipe rams and the blind rams will be function tested once each trip. The anticipated reservoir is expected to be less than 1300 psi, so the BOPE will be tested to 250 psi (Low) for 5 minutes and 1500 psi (High) for 10 minutes. Utilize a BOPE Testing Unit with a recording chart and appropriate test plug for testing. The drum brakes will be inspected and tested each tour. All tests and inspections will be recorded in the tour book as to time and results.

Jicarilla 93 #12B Operations Plan Page #2

#### III. MATERIALS

#### A. <u>CASING PROGRAM:</u>

CASING TYPE	HOLE SIZE	<u>DEPTH</u> (MD)	CASING SIZE	WT. & GRADE
Surface	14-3/4"	+/- 3 <b>2</b> 0'	10-3/4"	32.75# K-55
Production	9-7/8"	+/- 6,530'	7-5/8"	29.7# P-110
	9-7/8"	+/- 5,485'	7-5/8"	26.4# K-55

#### **B. FLOAT EQUIPMENT:**

- 1. <u>SURFACE CASING:</u> 10-3/4" notched regular pattern guide shoe. Run (1) standard centralizer on each of the bottom (3) joints of Surface Casing.
- <u>PRODUCTION CASING:</u> 7-5/8" cement nose guide shoe with a self-fill insert float. Place float collar one joint above the shoe. Install (1) Turbulent centralizer on each of the bottom (3) joints and one standard centralizer every (3) joints to 2,500 ft. Run (1) Turbulent centralizer at 2,700 ft., 2,500 ft., 2,300ft., 2,000ft., 1,500 ft., and 1,000 ft. (NTL-FRA 90-1).

# C. <u>CEMENTING:</u>

#### (Note: Volumes may be adjusted onsite due to actual conditions)

- <u>SURFACE:</u> Slurry: <u>200sx</u> (281 cu.ft.) of "Type III" + 2% CaCl<sub>2</sub> + ¼ # of cello-flake/sk (Yield = 1.39 cu.ft./sk, Weight = 14.5 #/gal.). The 100% excess should circulate cement to the surface. WOC 12 hours. Test csg to 1500psi.
- <u>PRODUCTION</u>: Lead <u>965 sx</u> (2,036) cu.ft.) of "Premium Light" with 8% gel, 4% Phenoseal and 1/4# cello-flake/sk (Yield = 2.11 cu.ft./sk, Weight = 12.1 #/gal.). Tail -<u>50 sx</u> (70cu.ft.) of "Type III" with 1/4# cello-flake/sk, (Yield = 1.4 cu.ft./sk, Weight = 14.5#/gal.) Use **50% excess in Lead Slurry** to circulate to surface. No excess in Tail Slurry. Total volume = 2,106 cu.ft. Bump Plug to 1,500 psi. Notify engineering if cement is not circulated to surface.

Jicarilla 93 #12B Operations Plan Page #3

# **IV COMPLETION**

# A. <u>CBL</u>

1. Run Cement Bond Log across all intervals to be perforated and find Top of Cement behind all casing strings if cement is not circulated to surface.

## B. PRESSURE TEST

1. Pressure test 7-5/8" casing to 3300# for 15 minutes.

# C. STIMULATION

- 1. Perforate the Point Lookout as determined from the open hole logs.
- 2. Stimulate with approximately 9,300# of 14/30 LiteProp<sup>TM</sup> sand in slick water.
- 3. Isolate Point Lookout with a CIBP.
- 4. Perforate the Menefee/Cliff House as determined from the open hole logs.
- 5. Stimulate with approximately 9,300# of 14/30 LiteProp<sup>TM</sup> sand in slick water.
- 6. Test each zone before removing bridge plugs.

# D. RUNNING TUBING

1. <u>Mesa Verde:</u> Run 2-3/8", 4.7#, J-55, EUE tubing with a SN (1.91" ID) on top of bottom joint. Land tubing approximately 25' above the bottom Point Lookout perforation.

Lang Huggin Gary Sizemore

Sr. Drilling Engineer