submiţted in lieu of	UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT		
· · · · · · · · · · · · · · · · · · ·	Sundry Notices and Reports on	Wells () ()	
1. Type of Well GAS		700 001 27 74 12: 6. 070 Farmington, N	If Indian, All. or
Name of Operator		7.	Unit Agreement Name
BURLINGT RESOURCE	. of Operator		Well Name & Number Canyon Largo Unit
4. Location of Well,	ington, NM 87499 (505) 326-97 Footage, Sec., T, R, M Sec.19, T-25-N, R-6-W, NMPM	10.	API Well No. 268 30039 2095 2 Field and Pool Ballard Pictured Clif County and State San Juan Co, NM
Type of Submission _X_ Notice of	Intent _X_ Abandonment Recompletion	Change of Pl New Construc	tion
X_ Notice of Subsequent Final Aban 13. Describe Propos It is intended	Intent X Abandonment Recompletion Report Plugging Back Casing Repair	Change of Pl New Construc Non-Routine F Water Shut o Conversion t	tion racturing ff o Injection
X_ Notice of Subsequent Final Aban 13. Describe Propos It is intended	Intent _X_ Abandonment	Change of Pl New Construc Non-Routine F Water Shut o Conversion t	tion racturing ff o Injection
X_ Notice of Subsequent Final Aban 13. Describe Propos It is intended procedure and	Intent _X Abandonment Recompletion Report Plugging Back Casing Repair Altering Casin_ Other Other ed or Completed Operations to plug and abandon the subject wellbore diagram.	Change of Pl New Construc Non-Routine F Water Shut o Conversion t t well according t	tion racturing ff o Injection o the attached

Plug and Abandonment Procedure 10/8/03 Canyon Largo Unit #268 Ballard Pictured Cliffs

1850' FNL, 1850' FEL NE, Sec. 19, T-25-N, R-6-W

Latitude: 36° 23.232" / Longitude: 107° 30.342" AIN: 4424601

Note: All cement volumes use 100% excess outside pipe and 50' excess inside. The stabilizing wellbore fluid will be 8.3 ppg, sufficient to balance all exposed formation pressures.

All cement will be ASTM Type II, mixed at 15.6 ppg with a 1.18 cf/sx yield.

- Install and test location rig anchors. Prepare blow pit. Comply with all NMOCD, BLM, and Burlington safety regulations. Conduct safety meeting for all personnel on location. NU relief line. Blow down well and kill with water as necessary. ND wellhead and NU BOP, test BOP.
- 2. Prepare 1-1/4" tubing workstring. Round-trip 2-7/8" gauge ring or casing scraper to 2685'.
- 3. Plug #1 (Pictured Cliffs perforations and Fruitland, Kirtland and Ojo Alamo tops, 2685' 1810'): RIH and set 2-7/8" wireline CIBP at 2685'. TIH with tubing worksting and tag CIBP. Pressure test casing to 500#. If casing does not test, then spot or tag subsequent plugs as appropriate. Mix 30 sxs cement (in two stages, casing leak?) to isolate the Pictured Cliffs perforations and cover through the Ojo Alamo top. PUH to 2130'.
- 4. Plug #2 (Nacimiento top and 8-5/8" casing shoe, 370' Surface): Perforate 3 bi-wire squeeze holes at 370'. Establish circulation out the bradenhead with water. Mix and pump approximately 130 sxs cement down 2-7/8" casing to circulate good cement out the bradenhead. Shut well in and WOC. [If the casing does not pressure test after plug #1, then determine the depth of the hole(s) with a pump around test or packer. Historically, holes have been found near the surface casing shoe in this Unit, and this may require a CR be used to cover the Nacimiento separately and then the casing shoe from 171' to surface.]
- 5. ND BOP and cut off casing below surface. Install P&A marker with cement to comply with regulations. RD, move off location, cut off anchors and restore location.

Recommended: Markauth	Approved:
Operations Engineer	Drilling Superintendent
//	

Office - (599-4043)

Engineer

Cell - (320-0321) Sundry Required: YES No

Lease Operator: Fred Garcia Cell:215-2722 Pager: 324-7418 Specialist: Sheldon Montoya Cell:320-2857 Pager: 326-8446 Foreman: Darren Randall Cell:320-2618 Pager: 324-7355

Approved:

Canyon Largo Unit #268

Current AIN #4424601

Ballard Pictured Cliffs

1850'N & 1850' E, Section 19, T-25-N, R-6-W, Rio Arriba County, NM

Lat: N: 36^ 23.232" / Long: W: 107^ 30.342" / API #30-039-20952

Today's Date: 10/08/03

Spud: 4/5/76 Completed: 7/29/76 Elevation: 6809' GL

Nacimiento @ 320'

12-1/4" Hole

8-5/8" 24# J-55 Casing set @ 121' Cement with 106 cf (Circulated to Surface)

TOC @ 1500' (T.S.)

Ojo Alamo @ 1860'

Kirtland @ 2080'

Fruitland @ 2350'

Pictured Cliffs @ 2678'

6-3/4" Hole

TD 3591'

Pictured Cliffs Perforations: 2735' - 2786'

2-7/8" 6.4#, H-40 Casing set @ 2828' Cement with 295 cf

Canyon Largo Unit #268

Proposed P&A

AIN #4424601

Ballard Pictured Cliffs

1850'N & 1850' E, Section 19, T-25-N, R-6-W, Rio Arriba County, NM

Lat: N: 36^ 23.232" / Long: W: 107^ 30.342" / API #30-039-20952

Today's Date: 10/08/03

Spud: 4/5/76 Completed: 7/29/76 Elevation: 6809' GL

Nacimiento @ 320'

12-1/4" Hole

8-5/8" 24# J-55 Casing set @ 121' Cement with 106 cf (Circulated to Surface)

Perforate @ 370'

Plug #2: 370' - Surface Cement with 130 sxs

TOC @ 1500' (T.S.)

Plug #1: 2685' - 1810' Cement with 30 sxs, (two 15 sxs stages)

Ojo Alamo @ 1860'

Kirtland @ 2080'

Fruitland @ 2350'

Pictured Cliffs @ 2678'

Set CIBP @ 2685'

Pictured Cliffs Perforations: 2735' - 2786'

2-7/8" 6.4#, H-40 Casing set @ 2828'

Cement with 295 cf

6-3/4" Hole

TD 3591'