Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

RECEIVED

FORM APPROVED OMB NO. 1004-0137 Expires July 31, 2010

MAR 00 2009

5. Lease Serial No.

Jicarilla Cont	tract 96
6 If Indian Allottee	

SUNDRY	NOTICES	AND	KEPOK 15	UN	WELLS	

Do not use this form for proposals to drill or to re-entered of Land Management

abandoned well. Use For	m 3160-3 (APD) for	such proposalmingto	on Field Office	Jicarilla Apache
SUBMIT IN TRIPLICATE - Other instructions on page 2			7. If Unit or CA/Agreement, Name and/or N 21938	
1. Type of Well Oil Well X Gas Well Other 2. Name of Operator				8. Well Name and No. Jicarilla 96 4R
Energen Resources Corporation				9. API Well No.
3a. Address		3b. Phone No. (<i>include ar</i>	rea code)	30-039-26855
2198 Bloomfield Highway, Farmington, NM 87401 505-325-6800			10. Field and Pool, or Exploratory Area	
4. Location of Well (Footage, Sec., T., R., M., or Survey	•		Ì	Blanco Mesaverde
1350' FNL, 2450' FWL, Sec. 01, T26	N, RO3W, N.M.P.N	1.	ŀ	
				11 County or Parish, State
				Rio Arriba NM
12. CHECK APPROPRIAT	E BOX(ES) TO IND	DICATE NATURE OF N	NOTICE, REPOI	RT, OR OTHER DATA
TYPE OF SUBMISSION		TY	PE OF ACTION	
Notice of Intent Subsequent Report	Acidize Alter Casing	Deepen Fracture Treat	Production Reclamation	(Start/Resume) X Water Shut-Off Well Integrity
	Casing Repair	New Construction	Recomplete	Other
Final Abandonment Notice	Change Plans	Plug and Abandon	Temporarily	y Abandon
	Convert to Injectio	n Plug Back	Water Dispo	osal
determined that the final site is ready for final insperiments. The sources intends to plug 1. MIRUFU. NDWH. NU the BOP. 2. POOH w/ the 2 3/8" tubing. TI 3. Mix and pump 12 sx. of cement 4. TIH w/ 7" CIBP and set at 4,0 5. Mix and pump 28 sx. of cement 6. RUWL and RIH to set a quick d 7. Perforate, acidize and fracture 8. TIH w/ tubing and clean out to 9. TIH w/ production equipment. 10. ND the BOP. NUWH. Clean located to the set and the set acidize acidize acidize acidize and the set acidize acid	whack the Jicari H w/ 4 1/2" CIBE con top of CIBP. 35'. Pressure to con top of CIBP. wrill bridge plug re Picture Cliff to bridge plug. Co ion. RDPUMO.	P and set at 5,529 Wait 4 hours and est to 1,000#. Wait 4 hours and 100' below proposits.	tag cement. tag cement. sed bottom po	POOH w/ tubing. erf in Picture Cliffs. g. RCVD MAR 13'09
14. I hereby certify that the foregoing is true and correct	HOLDOIOTT			
Name (Printed/Typed) Andrew Spto		Title Distri	ct Engineer	
Signature				
4880	S CRACE FOR FER:			
		ERAL OR STATE OF	FICE USE	Date MAR A C COAR
Approved by Original Signed: Ste	hugu masuu	Title		MAR 0 9 2009
Conditions of approval, if any, are attached. Approval of this not the applicant holds legal or equitable title to those rights in the sul entitle the applicant to conduct operations thereon		y that Office		