District I 1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Avenue, Artesia, NM 88210 District III
1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Revised October 10, 2003

Form C-141

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action								
API#30-045-32426	(OPERA T	ΓOR	al Report				
Name of Company BP America	$\overline{}$	Contact Donald Brooks						
Address 200 Energy Court	_	elephone No. (505) 326-9425						
Facility Name McCulley LS 004S	Fa	Facility Type Fruitland Coal Gas Well						
Surface Owner: Federal Mineral Owner			Lease No. NMNM04208					
LOCATION OF RELEASE								
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	rth/S	outh Line				County		
E 14 28N 09W 1490 Nor	rth		910	West		San Juan		
LatitudeLongitude								
NATURE OF RELEASE								
Type of Release: Gas - Fire		Volume of Release: N/A			Volume Recovered; N/A			
Source of Release; Seal on screw compressor		Date and Hour of Occurrence 1/25/2006 5:30 PM			Date and Hour of Discovery 1/25/2006 5:30 PM			
Was Immediate Notice Given?	\dashv	If YES, To Whom?				V	مرياليك	
☐ Yes ☐ No ☐ Not Required			Charlie Perrin					
By Whom? Kevin Hansford and Don Brooks		Date and Hour 1/26/2006 8:30 AM						
Was a Watercourse Reached? ☐ Yes ☒ No		Date and Hour 1/26/2006 8:30 AM If YES, Volume Impacting the Watercourse. FEB 2005 RECEIVED DIST. 8						
If a Watercourse was Impacted, Describe Fully.*								
If a Watercourse was Impacted, Describe Fully.*								
22.22.22								
Describe Cause of Problem and Remedial Action Taken.* When Hanover mechanic arrived on location he noticed a small flame coming out of the front								
seal on the screw compressor. The pill block had broken, causing the coupler to rub on guard and generating heat. The seal had a small amount of gas								
leaking, which was ignited by the heat on the coupling. We have asked the compression companies to look at a better guard design to prevent the rubbing should another pill block break.								
Describe Area Affected and Cleanup Action Taken.*								
No cleanup necessary.								
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and								
regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger								
public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability								
should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other								
federal, state, or local laws and/or regulations.								
N O O O			OIL CONSERVATION DIVISION					
Signature: Signature:)	4	11-7	utt.	
	\rceil_{A}	Approved by District Supervisor:					Dan &	
Printed Name: Donald Brooks	-	- +			so charte levin			
Title: Field Environmental Coordinator	A	Approval Date: 2/10/06 Expiration Date:						
E-mail Address: brooksd2@bp.com	_	Conditions of Approval:					_	
	┧ ~	onamons o	pp.o.ui.			Attached		
Date: 2/9/2006 Phone: 326-9425	-					1		

* Attach Additional Sheets If Necessary

NDGF0604154681