District I 1625 N French Dr , Hobbs, NM 88240 District II 1301 W Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 1220 S St Francis Di, Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources



side of form

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Release Notification and Corrective

	30	045-	37		OPERA	TOR	Ell a.	☐ Initi	ial Report	X Final Re	eport	
Name of Company XTO Energy Inc.						OPERATOR Contact Lisa Winn Telephone No. (505) 566-7942 Inutial Report X Final Report						
Address 2700 Farmington Ave, Bldg K, Ste. 1,						Telephone No. (505) 566-7942						
Farmington, NM 87401												
Facility Name LC Kelly #3G						Facility Type Gas Well						
Surface Owi	ner BLM		Mineral C	wner 1	BLM		Lease No. NMSF081239					
				LOCA	TION	N OF REI	LEASE					
Unit Letter	Section	Township	Range	Feet from the		South Line	Feet from the	East/W	est Line	County		_
В	4	30N	12W	690	North	2165 East		East		San Juan		
		L		atituda 26.94	<i>C</i> 5	T anaituda	L					
Latitude 36.8465 Longitude 108.101722												
NATURE OF RELEASE												
Type of Relea					Volume of Release Approx 20 bl							
Source of Rel	ease Prod	uction tank			Date and Hour of Occurrence 08/18/06, time unknown			Date and Hour of Discovery 08/18/06 at 9:00 am				
Was Immediate Notice Given?						16 YES, To Whom?						
			☐ No X Not Ro	equired								
By Whom?						Date and Hour						
Was a Watercourse Reached?						If YES, Volume Impacting the Watercourse.						
			No									
If a Watercourse was Impacted, Describe Fully *												
N/A												
Describe Cause of Problem and Remedial Action Taken * A faulty ignition switch and wiring on the pumping unit motor caused the pit tank to												
overflow resulting in a spill of approximately 20 bbl of clear produced water. The spill was contained within the secondary containment												
structure, the water clear without sheen of hydrocarbon on the water. No further remedial action is recommended at this time.												
Describe Area Affected and Cleanup Action Taken * There did not appear to be lateral migration of the spill beyond the secondary containment. The spill was detected promintly and a vacuum truck immediately recovered the vector within the borm walls. Quick response resulted in recovery.												
The spill was detected promptly and a vacuum truck immediately recovered the water within the berm walls. Quick response resulted in recovery of water and no observed impact to the location.												
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and												
regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger												
public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability												
should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health												
or the environment In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, gr-local laws and/or regulations.												
						OIL CONSERVATION DIVISION						
Signature. All Williams												
	,	<u> </u>			Approved by District Supervisor: Branchon Denell For: Charlie Perrin							
Printed Name	: Lisa Wii	nn				District Supervise		reson l	ones	1517	in	
Title: Enviro	nmental S	pecialist			Approval Date. 8/24/06 Expiration Date:							
E-mail Addre	ss. Lisa_V	Vinn@xtoene		(Conditions of Approval:				Attached			

Phone: 505-566-7942

08/24/06

Date:

^{*} Attach Additional Sheets If Necessary