District I 1625 N French Dr , Hobbs, NM 88240 District II 811 South First, Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505 State of New Mexico
Energy Minerals and Natural Resources

Form C-141 Revised March 17, 1999

Oil Conservation Division 1220 South St. Francis Di Santa Fe, NM 8

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action										
30039 25466 OPERATOR CO. Deligial Repo									oort	
Name of Company BP Contact Brittany Bentso \\										
Address 200 Energy Court, Farmington, NM 87401 Telephone No. (505) 326-9235										·
Facility Name Carracas Canyon Unit 34-B9 Facility Type Well site										
Surface Owner Forest Service Mineral Owner						BLM		Lease No. 678696		e No. 678696
LOCATION OF RELEASE										
Unit Letter I	Section 34	Township 32N	Range 4W	Feet from the	North/S	South Line	Feet from the	East/West Line		County Rio Arriba
NATURE OF RELEASE										
Type of Release Produced Water from a gathering line							Volume of Release 50 bbls Volume Recovered 40 bbls			
Source of Release						Date and Hour of Occurrence Date and Hour of Disco			- 1	
Produced Water Gathering Line Was Immediate Notice Given?						07/13/2001 4:30 pm If YES, To Whom?				
Yes No Not Required						Henry Villenueva				
By Whom? Greg Nelson						Date and Hour 07/13/2001 5:00 pm				
Was a Watercourse Reached? Yes No						If YES, Volume Impacting the Watercourse. About 40 bbls				
of the well pad. The produced water accumulated in the stock pond. Upon discovery, a water sample was taken and the pond was drained. The water is currently being tested to determine if the top layer of soil in the bottom of the pond will need to be removed. The cattails in the pond do not appear to have suffered any damage. Describe Cause of Problem and Remedial Action Taken.* The cause of the gathering line leak is still being investigated. A vactron was used to uncover the pipe and the pipe is currently being inspected. Past incidents in Carracas, indicate that the piping was installed incorrectly resulting in damage by rocks. We are still trying to determine if that is the cases in this incident. Describe Area Affected and Cleanup Action Taken.* The produced water and other water in the stock pond was drained and tests are being performed on a water sample to determine if a layer of soil should be removed from the bottom of the pond. Thereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. OIL CONSERVATION DIVISION										
Signature: Dutte D. Blake						Deny Jon				
Printed Name: Brittany D. Benko						Approved by District Supervisor: For Frank Chavez				
Title: Fil	ld En	vironm	unta	Coordina	ator	Approval I	Date: 7/24	12001	Expiratio	on Date:
	20/01		Phone:	326-923	35	1	, ,			
Date: 7 20 01 Phone: 326-9235 Conditions of Approval: Comply with Attached * Attach Additional Sheets If Necessary Forest Service Requirments										
						n DG	F01205	5579	8	