


District I
1655 N. French Dr., Hobbs, NM 88240
District II
811 South First, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised March 17, 1999

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form



Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company BP	Contact Brittany Benko
Address 200 Energy Court, Farmington, NM 87401	Telephone No. (505) 326-9235
Facility Name Arnaud A #3	Facility Type Well site

Surface Owner BLM	Mineral Owner BLM	Lease No. 186319 Fed NMSV078513
--------------------------	--------------------------	---

LOCATION OF RELEASE

Unit Letter P A	Section 20	Township 32N	Range 19W 9W	Feet from the	North/South Line	Feet from the	East/West Line	County San Juan
---------------------------	----------------------	------------------------	----------------------------------	---------------	------------------	---------------	----------------	---------------------------

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 85 bbls	Volume Recovered 80 bbls
Source of Release Produced Water Pit	Date and Hour of Occurrence	Date and Hour of Discovery 20/08/2001 10:30am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Denny Foust	
By Whom? Brittany Benko	Date and Hour 08/21/2001 8:20 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. NA	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* **The dump on the separator hung closed and caused water to carry over to the compressor scrubber. The scrubber dumps to a 95 bbl pit. Produced water filled the pit and over flowed into the hole around the pit resulting in a spill of 85 bbls of produced water. A Vac truck was called and recovered 80 bbl of produced water.**

Describe Area Affected and Cleanup Action Taken.* **The only area effected was the soil inside of the wood cellar surrounding the pit. A Vac truck recovered 80 bbls of the produced water.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Brittany D. Benko	OIL CONSERVATION DIVISION	
Printed Name: Brittany D. Benko	Approved by District Supervisor: Denny Foust for Frank Chavez	
Title: Environmental Coordinator	Approval Date: 9/4/01	Expiration Date:
Date: 8/30/01	Phone: 326-9235	Conditions of Approval:
		Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary

n DG-F0123432089

August 30, 2001

Bureau of Land Management
1235 La Plata Highway
Farmington, NM 87401
Attn: Mr. Mark Kelly

RE: Arnaud A #3 Produced Water spill, Lease NMSV078513

Dear Mr. Kelly:

Confirming my phone call to your office on Tuesday August 21, 2001 at 8:30 am, a produced water spill occurred at the Arnaud A #3, a wellsite located in Unit P Section 20 T32N-R19W, San Juan County, New Mexico. The lease number is NM SV 078513. The spill was discovered at 10:30 am on August 20, 2001. The dump on the separator hung closed and caused water to carry over to the compressor scrubber. The scrubber dumps to a 95 bbl pit. Produced water filled the pit and over flowed into the hole around the pit resulting in a spill of 85 bbls of produced water. A Vac truck was called and recovered 80 bbl of produced water. The spill did not leave the wellsite location and, consequently, did not enter a waterway.

Should you have any additional questions, please feel free to contact either Brittany Benko at 326-9235 or Buddy Shaw at 326-9219 in our Farmington office.

Sincerely,



Brittany Benko
Environmental Coordinator

cc: New Mexico Oil Conservation Division
1000 Rio Brazos Rd
Aztec, NM 87410
Attn: Mr. Denny Foust