District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico

Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr
Santa Fe, NM 87505

Form C-141 Revised March 17, 1999

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action 3						
3004528549	\mathbf{O}	PERATO	R YC.	X□ Initiâl.	Report X Final Report	
Name of Company	,	Contact □ R.	A. Wirtanen	62 97 15 07 26 58		
Phillips Petroleum Company Address	Contact □ R. A. Wirtahen Contact □ R. A. Wirt					
5525 Hwy. 64 Farmington, NM 87401			Telephone No. 1303-399-3402			
			Facility Type□ SWD well			
San Juan 32-7 #301 SWD						
rface Owner Mineral Owner				Lease N	Lease No.□NMSF078998	
Bureau of Land Management Bureau of Land		Management				
LOCATION OF RELEASE						
Unit Letter Section Township Range Fee M 34 32N 7W	et from the North	/South Line		East/West Line West	County□ San Juan	
NATURE OF RELEASE						
Type of Release		Volume of Release		Volume R	Volume Recovered □ 216 bbls	
Produced Water Source of Release		Date and H	our of Occurrence	urrence Date and Hour of Discovery 12/10/01		
Staininless steel tubing came loose behind WH		12/09/01 @ 2:00 PM				
Was Immediate Notice Given? X Yes □ No □ Not Required		If YES, To Whom? BLM – Mark Kelly, NMOCD – Denny Foust;				
By Whom?		Date and Hour □ 12/10/01 @ 1330 hrs				
Patsy Clugston – Sr. Regulatory Clerk						
Was a Watercourse Reached?		If YES, Vo	lume Impacting the	Watercourse.		
☐ Yes X No			N/A			
If a Watercourse was Impacted, Describe Fully.*						
A watercourse was not reached.						
Describe Cause of Problem and Remedial Action Taken.*						
The door on the meter house was left open and the cataylitic heater was not running, must of started chattering causing the 3/8" tubing to come loose from the back of the wellhead. Approx. 240 bbls of water spilled through a line. Approximately 216 bbls of water has been picked up						
making about 90% recovery. The catalyitic heater will be repaired or replaced and maintained the doors stay closed to the builing.						
Describe Area Affected and Cleanup Action Taken.*						
location						
Spilled water did not leave the lease. Approx. 216 bbls of water was sucked up and properly disposed of.						
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and						
regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability						
should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health						
or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other						
federal, state, or local laws and/or regulations.						
KAWI			OIL CONSERVATION DIVISION			
Signature: Original signed by Patsy Chigston			Approved by District Supervisor: Co Fig. 16 Character			
Printed Name: Patsy Clugston	Approved by	District Superviso	r: for	Frank Charez		
Title: Sr Safaty & Environmental Specialist	Approval Dat	12/14/01	Evaluation	Doto		
Title: Sr. Safety & Environmental Specialist	Approvai Dai	c. 10/1/01	Expiration	Date.		

Phone: 505-599-3454

12/10/01

Attached