

District SOUTH	Field Name ALBINO PICTURED CLIFFS	API / UWI 3003930819	County RIO ARRIBA	State/Province NEW MEXICO	
Original Spud Date 4/19/2010	Surface Legal Location 035-028N-005W-J	East/West Distance (ft) 2,090.00	East/West Reference FEL	North/South Distance (ft) 1,900.00	North/South Reference FSL

Well Config: DEVIATED - Original Hole, 11/24/2010 8:09:33 AM

ftKB (MD)

Schematic - Actual

16	3-2, Casing Joints, 4 1/2, 4,000, 16
17	3-1, Casing Pup Joint, 4 1/2, 4,000, 16
17	2-1, Casing Joints, 7, 6,366, 16
19	3-3, Casing Hanger, 4 1/2, 4,000, 16, 0.6
26	2-2, Casing Hanger, 7, 6,366, 16, 1.5
28	1-1, CASING HANGER, 9 5/8, 9,001, 16, 3.3
54	3-4, Casing Pup Joint, 4 1/2, 4,000, 17, 9.3
229	2-3, Casing Pup Joint, 7, 6,366, 18, 10.0
229	3-5, Casing Pup Joint, 4 1/2, 4,000, 26, 28.0
235	1-2, CASING JOINTS, 9 5/8, 9,001, 19, 209.3
2,806	1-3, SAW TOOTH COLLAR, 9 5/8, 9,001, 229, 0.8
3,306	2-4, Casing Joints, 7, 6,366, 28, 3,278.6
3,309	2-5, Stage Tool, 7, 6,366, 3,306, 2.5
4,284	1-1, Tubing, 2 3/8, 1,995, 16, 8,083.7
4,291	3-6, Casing Joints, 4 1/2, 4,000, 54, 4,230.2
4,292	2-6, Casing Joints, 7, 6,366, 3,309, 982.2
4,331	2-7, Float Collar, 7, 6,366, 4,291, 0.9
4,333	2-8, Casing Joints, 7, 6,366, 4,292, 39.4
4,348	2-9, Float Shoe, 7, 6,366, 4,331, 1.8
4,455	3-7, Casing Joints, 4 1/2, 4,000, 4,284, 170.6
4,465	3-8, Marker Joint, 4 1/2, 4,000, 4,455, 9.7
4,815	Perforated, 4,815-5,322, 7/26/2010
5,322	Perforated, 5,425-5,797, 7/26/2010
5,425	Perforated, 5,859-6,487, 7/26/2010
5,797	Perforated, 8,046-8,126, 7/24/2010
5,859	1-2, Tubing, 2 3/8, 1,995, 8,100, 2.0
6,487	1-3, Tubing, 2 3/8, 1,995, 8,102, 30.6
7,874	1-4, Profile Nipple, 2 3/8, 1,785, 8,132, 1.1
7,884	1-5, Mule Shoe, 2 3/8, 1,785, 8,133, 1.0
8,046	Perforated, 8,143-8,240, 7/24/2010
8,100	3-11, Casing Joints, 4 1/2, 4,000, 7,884, 382.5
8,102	3-12, Float Collar, 4 1/2, 4,000, 8,267, 0.6
8,126	3-13, Float Shoe, 4 1/2, 4,000, 8,267, 0.8
8,132	
8,134	
8,135	
8,143	
8,240	
8,250	
8,267	
8,267	
8,268	
8,270	

RCVD DEC 7 '10

OIL CONS. DIV.

DIST. 3