

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

APR 30-045-26137

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company BP America	Contact Kevin Hansford
Address 200 Energy Court	Telephone No. (505) 326-9279
Facility Name Houck GC C1E	Facility Type Gas Well

Surface Owner: Federal	Mineral Owner	Lease No. NMNM073922
------------------------	---------------	----------------------

LOCATION OF RELEASE

Unit Letter C	Section 6	Township 29N	Range 09W	Feet from the 790	North/South Line North	Feet from the 1365	East/West Line West	County San Juan
------------------	--------------	-----------------	--------------	----------------------	---------------------------	-----------------------	------------------------	--------------------

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release: Condensate	Volume of Release: 20 barrels	Volume Recovered: <1 barrel
Source of Release: Condensate Tank	Date and Hour of Occurrence 5/8/2006 3:00 PM	Date and Hour of Discovery 5/8/2006 3:00 PM
Was Immediate Notice Given? ☐ Yes ☐ No ☒ Not Required	If YES, To Whom? NA	
By Whom?	Date and Hour	
Was a Watercourse Reached? ☐ Yes ☒ No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* Construction crew pulled onto location and discovered oil running from the top of the condensate tank on location. They shut the well in and notified BP. 20 barrels of condensate were released with very little recovered. The condensate tank also had a large amount of water in it, indicating a problem with the separator. The high tank alarm also failed to activate.


Describe Area Affected and Cleanup Action Taken.* The impacted soils were excavated and taken to BP's Crouch Mesa Landfarm for treatment, clean soil was hauled in to replace the excavated soil and the separator was repaired. The clean up work was completed during the week of 6/26/06.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

		OIL CONSERVATION DIVISION	
Signature:		Approved by District Supervisor: <i>Brandon Penell</i> For: <i>Charlie Perrin</i>	
Printed Name: Kevin Hansford			
Title: Field Environmental Coordinator	Approval Date: 7/7/06	Expiration Date:	
E-mail Address: hanske@bp.com	Conditions of Approval:	Attached ☐	
Date: 5/16/2006	Phone: 326-9279		

* Attach Additional Sheets If Necessary

nBP 0619432000



4

HOUCK GC C O 1E-DK
API# 3004526137
FEDERAL LEASE# NMNM073922
NE/4 NW/4 (C) S.6-T29N-R9W
SAN JUAN COUNTY ELEV 5774
BP AMERICA PRODUCTION COMPANY
LAT 36.75913 LONG 107.82261

