


District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 South First, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
2040 South Pacheco
Santa Fe, NM 87505



Form C-141

Revised March 17, 1999

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

30 039 2530

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company Black Hills E&P/ Mallon Oil Company	Contact: Buck Pruitt
Address: P.O. Box 249, 3200 N 1 st St., Bloomfield, N.M. 87413	Telephone No: (505) 634-1111 Ext. 24
Facility: Jic. 30-03-28 #1	Facility Type: Natural Gas Well

Surface Owner Jicarilla Apache Res.	Mineral Owner Jicarilla Apache Res.	Lease No. 701-90-0002
--	--	-----------------------

LOCATION OF RELEASE

Unit Letter D	Section 28	Township 30N	Range 03W	Feet from the 1185'	North/South Line South	Feet from the 790'	East/West Line West	County Rio Arriba
------------------	---------------	-----------------	--------------	------------------------	---------------------------	-----------------------	------------------------	----------------------

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 85 BBL Est.	Volume Recovered: 83 BBls Est.
Source of Release: Water transfer pipeline.	Date and Hour of Occurrence: 11/25/03 @ approx. 0200 hrs.	Date and Hour of Discovery: 11/25/03 @ approx. 0900 hrs.
Was Immediate Notice Given? Yes	If YES, To Whom? Buck Pruitt, BHEP	
By Whom? Randy Thompson, BHEP	Date and Hour: 11/25/03 @ approx. 0920 hrs.	
Was a Watercourse Reached? No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully. * N/A

Describe Cause of Problem and Remedial Action Taken. * A (2") two inch steel pipe nipple broke, due to freezing, allowing produced water to escape from the produced water gathering system. No Remedial action was taken.

Describe Area Affected and Cleanup Action Taken: * The leak occurred at the tank, on the water transfer pumps suction piping, located inside the bermed containment surrounding the storage tank. A vacuum truck recovered most of the water and the unrecoverable balance was left to evaporate. The piping configuration was altered, as well, so as to help prevent this failure from reoccurring.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remedial contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Buck Pruitt</i>	OIL CONSERVATION DIVISION	
Printed Name: Buck Pruitt	Approved by District Supervisor: <i>for Frank Chavez</i>	
Title: District Production Foreman	Approval Date: 11/05/03	Expiration Date:
Date: 11/28/03	Phone: (505) 486 - 0330	Conditions of Approval: <i>Original filing lost in mail.</i>
		Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary

~~ADGF 0400534030~~
ADGF 0408539275