

SFPRR 9783 #43

D-27-20N-9W

GEO ENGINEERING INC.

P

30-031-20900

1-21-86

F. Loc. 300/N; 165/W Elev. 6421 GL Spd. _____ Cu. ft. _____ Comp. _____ TD _____ PB _____
 Casing S. _____ @ _____ W _____ Sx. Int. _____ @ _____ W _____ Sx. Pr. _____ @ _____ W _____ Sx. T. _____ @ _____
 Csg. Perf. _____ Prod. Stim. _____

T Gas
R
A
N
S

I.P. _____ BO/D _____ MCF/D After _____ Hrs. _____ SICIP _____ PSI After _____ Days GOR _____ Grav. _____ 1st Del. Gas _____
 1st Del. Oil _____

TOPS	NI/TD X	Well Log	TEST DATA							Ref. No.
Ojo Alamo	C-103	Plot X	Schd.	PC	Q	PW	PD	D		
Kirtland	C-104	Electric Log								
Fruitland		C-122								
Pictured Cliffs	Ditr	Dfa								
Chacra	Datr	Doc								
Cliff House										
Menefee										
Point Lookout										
Mancos										
Gallup										
Greenhorn										
Dakota										
Entrada										
		Acres 40								

P
o
i

ChacoWashMV Co. MCK S 27 T 20N R 9W U D Oper. Geo-Engineering Inc. Loe. SFPRR 9783 No. 43



TONEY ANAYA
GOVERNOR

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT
OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE

1000 RIO BRAZOS ROAD
AZTEC, NEW MEXICO 87410
(505) 334-6178

March 21, 1986

Mr. Jim Law
Geo-Engineering, Inc.
P.O. Box 2966
Santa Fe, NM 87504

Re: SFPRR 9783 #43, D-27-20N-09W

Dear Mr. Law:

Due to inadequate bonding, your permit to drill the referenced well has been cancelled. If at some later date, you wish to commence drilling operations, it will be necessary to submit proof of bonding and a new application for permit to drill.

Yours truly,

A handwritten signature in cursive script, appearing to read "Carolyn J. Taplin".

Carolyn J. Taplin
Field Representative

CJT/dj

xc: Prentiss Childs
Jeff Taylor
UIC File
Well File
Operator File

ABANDONED OPERATION