

(November 1983)
(Formerly 9-331)

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIP
(Other instruction
verse side)

DATE

Budget Bureau No. 1004-013
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

SF- 078562

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Lybrook

9. WELL NO.

2

10. FIELD AND POOL, OR WILDCAT

Escrito Gallup

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

22-24N - 7 W

12. COUNTY OR PARISH 13. STATE

Rio Arriba

N.Mex.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1.

OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

BCO, INC.

3. ADDRESS OF OPERATOR

135 Grant Avenue, Santa Fe, New Mexico 87501

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

2060 FSL 660 FEL Sec 22; T24N R7W N.M.P.M.

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

6748 Gr.

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANE

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Believe well has casing failure. Intend to locate failure and repair. Intend to drill out cement and place well back in production.

Well was drilled in 1960 and 4 1/2" casing was set at 5674'. Casing was cemented with 150 sacks cement. Well was completed in following intervals: 5564-92, 5434 - 5460, 5378 - 5394. In 1978 repaired hole in casing located between 2040 and 2090 with 150 sacks of cement. In 1988 repaired hole in casing located between 514 - 780 with 300 sacks of cement. In 1989 repaired hole in casing located between 1847 and 1870 with 150 sacks cement.

RECEIVED

AUG 14 1991

OIL CON. DIV.
DIST. 3

18. I hereby certify that the foregoing is true and correct

SIGNED Elizabeth B. Keeshan TITLE President

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

MMOOD

*See Instructions on Reverse Side

APPROVED

DATE July 16, 1991

AUG 07 1991

DATE

AREA MANAGER
FARMINGTON RESOURCE AREA