
In April 1974 set bridge plus Gallup watered off. Perforated wis 5989-90, 5997-6010 and 6030-36. May 1974 squeezed casing failure is cement. Repaired hole in tubing March ffin April 3, 1990, by pumping the casing. Recovered all drip in one between casing and pump. Filled when attempted to treat for paraffattributed to gas bubble. Recover part on July 16, 1990. Repaired 18. I hereby certify that the foregoing is true and correct	g at 6100' when May th two shots per for the set cement retainer between 2150 & 2180 and the set of	oot at 5934-44, at 6020. In with 200 sacks ed well for para- drip down communication barrels of drip Field personnel s before had rod
In April 1974 set bridge plus Gallup watered off. Perforated with 5989-90, 5997-6010 and 6030-36. May 1974 squeezed casing failure is cement. Repaired hole in tubing March ffin April 3, 1990, by pumping the casing. Recovered all drip in one between casing and pump. Filled when attempted to treat for paraffattributed to gas bubble. Recover part on July 16, 1990. Repaired 18. I hereby certify that the foregoing is true and correct signed Example 1990. (This space for Federal or State office use)	g at 6100' when May th two shots per for the set cement retainer between 2150 & 2180 and 29, 1990. Treated and so know had consing with thirty fin July 10, 1990. The red nineteen barrely rods and put to pure the set of t	oot at 5934-44, at 6020. In with 200 sacks ed well for para- communication barrels of drip Field personnel as before had rod p July 31, 1990.
In April 1974 set bridge plus Gallup watered off. Perforated wis 5989-90, 5997-6010 and 6030-36. May 1974 squeezed casing failure is cement. Repaired hole in tubing March ffin April 3, 1990, by pumping the casing. Recovered all drip in one between casing and pump. Filled when attempted to treat for paraffattributed to gas bubble. Recover part on July 16, 1990. Repaired 18. I hereby certify that the foregoing is true and correct SIGNED Examples 1975.	g at 6100' when May th two shots per for the set cement retainer between 2150 & 2180 and 29, 1990. Treated and so know had consing with thirty fin July 10, 1990. The red nineteen barrely rods and put to pure the set of t	oot at 5934-44, at 6020. In with 200 sacks ed well for para- communication barrels of drip Field personnel as before had rod p July 31, 1990.
In April 1974 set bridge plus Gallup watered off. Perforated wis 5989-90, 5997-6010 and 6030-36. May 1974 squeezed casing failure is cement. Repaired hole in tubing March ffin April 3, 1990, by pumping the casing. Recovered all drip in one between casing and pump. Filled when attempted to treat for paraffattributed to gas bubble. Recover part on July 16, 1990. Repaired 18. I hereby certify that the foregoing is true and correct	g at 6100' when May th two shots per for the set cement retainer between 2150 & 2180 and 29, 1990. Treated and so know had consing with thirty fin July 10, 1990. The red nineteen barrely rods and put to pure the set of t	oot at 5934-44, at 6020. In with 200 sacks ed well for para- communication barrels of drip Field personnel as before had rod p July 31, 1990.
In April 1974 set bridge pluce Gallup watered off. Perforated with 5989-90, 5997-6010 and 6030-36. May 1974 squeezed casing failure becament. Repaired hole in tubing March fin April 3, 1990, by pumping the casing. Recovered all drip in one between casing and pump. Filled when attempted to treat for paraffattributed to gas bubble. Recover part on July 16, 1990. Repaired	g at 6100' when May th two shots per for the set cement retainer between 2150 & 2180 and the set of	oot at 5934-44, at 6020. In with 200 sacks ed well for para- drip down communication barrels of drip Field personnel s before had rod
In April 1974 set bridge pluce Gallup watered off. Perforated with 5989-90, 5997-6010 and 6030-36. May 1974 squeezed casing failure becament. Repaired hole in tubing March ffin April 3, 1990, by pumping the casing. Recovered all drip in one between casing and pump. Filled when attempted to treat for parafactuributed to gas bubble. Recovered	g at 6100' when May th two shots per for the set cement retainer between 2150 & 2180 and the set of	oot at 5934-44, at 6020. In with 200 sacks ed well for para- drip down communication barrels of drip Field personnel s before had rod
In April 1974 set bridge pluce Gallup watered off. Perforated with 5989-90, 5997-6010 and 6030-36. So May 1974 squeezed casing failure becament. Repaired hole in tubing March fin April 3, 1990, by pumping the casing. Recovered all drip in one between casing and pump. Filled of when attempted to treat for parafic	g at 6100' when May ith two shots per f Set cement retainer between 2150 & 2180 n 29, 1990. Treate irty-one barrels of e day so know had coasing with thirty fin July 10, 1990.	oot at 5934-44, at 6020. In with 200 sacks ed well for para- drip down communication barrels of drip Field personnel
In April 1974 set bridge pluce Gallup watered off. Perforated with 5989-90, 5997-6010 and 6030-36. So May 1974 squeezed casing failure because the cement. Repaired hole in tubing March fin April 3, 1990, by pumping the casing. Recovered all drip in one between casing and pump. Filled of	g at 6100' when May th two shots per f Set cement retainer between 2150 & 2180 n 29, 1990. Treate irty-one barrels of e day so know had casing with thirty	oot at 5934-44, at 6020. In with 200 sacks ed well for para- communication barrels of drip
In April 1974 set bridge plug Gallup watered off. Perforated with 5989-90, 5997-6010 and 6030-36. So May 1974 squeezed casing failure becement. Repaired hole in tubing March ffin April 3, 1990, by pumping the	g at 6100' when May th two shots per for the set cement retainer between 2150 & 2180 n 29, 1990. Treate irty-one barrels of	oot at 5934-44, at 6020. In with 200 sacks ed well for para- drip down
In April 1974 set bridge plug Gallup watered off. Perforated with 5989-90, 5997-6010 and 6030-36. May 1974 squeezed casing failure cement. Repaired hole in tubing March	g at 6100' when May ith two shots per f Set cement retainer between 2150 & 2180 n 29, 1990. Treate	oot at 5934-44, at 6020. In with 200 sacks ed well for para-
In April 1974 set bridge plug Gallup watered off. Perforated with 5989-90, 5997-6010 and 6030-36. S May 1974 squeezed casing failure is cement.	g at 6100' when May ith two shots per f Set cement retainer petween 2150 & 2180	oot at 5934-44, at 6020. In with 200 sacks
In April 1974 set bridge plug Gallup watered off. Perforated with 5989-90, 5997-6010 and 6030-36. S May 1974 squeezed casing failure	g at 6100' when May ith two shots per f Set cement retainer	oot at 5934-44, at 6020. In
four shots per foot from 6128-6144 In April 1974 set bridge plug Gallup watered off. Perforated wide 5989-90, 5997-6010 and 6030-36.	g at 6100' when May ith two shots per f Set cement retainer	oot at 5934-44, at 6020. In
four shots per foot from 6128-6144 In April 1974 set bridge plug Gallup watered off. Perforated with	g at 6100' when May ith two shots per f	oot at 5934-44,
four shots per foot from 6128-6144 In April 1974 set bridge plus	at 6100' when May	re member of
four shots per foot from 6128-6144		
four shots per foot from 6128-6144		
tir ittiller i v temelli en willi i / i soloks	and 6172-6178.	
Well was drilled in 1961. Ca originally cemented with 175 sacks	ising (4 1/2" set a	erforated with
•		+ 62201) *****
9/24/90.	-	
Called and discussed intent to plu	g with Steve Mason	of the BLM on
9/25/90 Have determined it is ne	cessary to plug an	d abandon well.
nent to this work.) *	mons and measured and true vertica	depens for all markers and zones perti-
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertine) proposed work. If well is directionally drilled, give subsurface location nent to this work.)*	. 4 1	
(Other)	(Note: Report results	of multiple completion on Well
REPAIR WELL CHANGE PLANS	(Other)	ABANDON MENT*
FRACTURE TREAT MULTIPLE COMPLETE SHOOT OR ACIDIZE ARANDON*	FRACTURE TREATMENT	ALTERING CASING
TEST WATER SHUT-OFF PULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING WELL
NOTICE OF INTENTION TO:	SUBSEQU	ENT REPORT OF:
16. Check Appropriate Box To Indicate 1	Nature of Notice, Report, or C	ther Data = (BIII = #4)
	V. (N. D. G	
GL 7280	,	
14. PERMIT NO. 15. ELEVATIONS (Show whether D	F, RT, GR, etc.)	18-24N-7W NMPM 12. COUNTY OR PARISH 13. STATE
1650 FNL 2310 FEL 18-24N-7W	NMPM	10 0/15
1650 FNL 2310 FET. 18-24N-7W		11. SEC., T., R., M., OR BLE, AND SURVEY OR AREA
At surface		Escrito Gallup
4. LOCATION OF WELL (Report location clearly and in accordance with any See also space 17 below.)	State requirements.*	10. FIELD AND POOL, OR WILDCAT
135 Grant, Santa Fe, New Mexico 87	501	7 TOTAL TOTAL
BCO, Inc. 3. ADDRESS OF OPERATOR		Escrito Unit:
NICT 2	A FallyGreat, March French	8. FARM OR LEASE NAME.
WELL KX WELL OTHER OIL CON. D	V.	Escrito
1. OIL GAS GAS		7. UNIT AGREEMENT NAME
(Do not use this form for proposals thill or to deepen or plug Use "APPLICATION R PERMIT—" for	baci a different reservoir.	
SUNDRY NOTICE LA MOURE ORTS	ON VELLS	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
		/NM-03595 = 3 = 3
GEOLOGICAL SURVEY	IOR (Other instructions on reverse side)	Budget Bureau No. 42-R1424. 5. LEASE DESIGNATION AND SERIAL NO.
GEOLOGICAL SHRYEM		Form approved
TAN IS IT IS	SUBMIT IN TRIPLICATE.	, COPTES
DEPARTMENT OF THE INTER	SUBMIT IN TRIPLICATE*	7 Copies



Operator: BCO, Inc.

135 Grant Avenue Santa Fe, NM 87501

SUNDRY NOTICES AND REPORTS ON WELLS

Lease No.: NM-03595

Page Two

Hot oiled down tubing with thirty-nine barrels which was recovered in two days. On September 10, 1990, attempted to treat paraffin with drip. Casing filled with six and one half barrels. Pumped an additional seven and one half barrels at 650 pounds. Did not show any extra production to indicate recovery of drip. Believe that between April 3, 1990, when had communication between casing and pump and July 10, 1990 when casing filled with thirty barrels, well had casing failure. We believe a bridge has formed that prevents communication between the casing and pump. We believe the most likely place for bridge to form is at tubing tie down which is attached to the twelfth joint of tubing run into the hole about 5298. We may encounter special problems if we have difficulty unseating pump and/or unseating tubing tie down and pulling tubing.

We do not intend to pull casing. Will set cement plugs with perforations and length of plug as designated by BLM. Will fill inside of casing between plugs with cement. Will restore surface and set dry hole marker in compliance with BLM regulations. Will reseed in 1991.

	÷.	

UNITED STATES DEPARTMENT OF THE INTERIOR

BUREAU OF LAND MANAGEMENT FARMINGTON RESOURCE AREA 1235 LA PLATA HIGHWAY FARMINGTON, NEW MEXICO 87401

Attachment to Notice of

Re: Permanent Abandonment

Intention to Abandon

CONDITIONS OF APPROVAL

1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal Leases."

- Mark Kelly with the Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 326-6201.
- Blowout prevention equipment is required.
- The following modifications to your plugging program are to be made (when applicable): Plus:
 - 1) Gallup from 6100 5500
 - 2) Mesaverd from 4150 4050 inside + ourside 4 1/2 Cesting +100% excess
 3) Cheirn from 3083 2983 " " "

 - 4) Procured Cliffs & Fruitfund from 2658 - 2350
 - 5) Ojo Hlamo from 2037 1860
 - 6) Nuclimiento & Surface Casing Shoe & Surface plug from 418 - Surface

Office Hours: 7:45 a.m. to 4:30 p.m.

GENERAL REQUIREMENTS FOR PERMANENT ABANDONMENT OF WELLS ON FEDERAL AND INDIAN LEASES FARMINGTON RESOURCE AREA

- 1. Secure prior approval either on a Sundry Notice (Form 3160-5) or verbally from the Fluids Drilling & Production Section at this office before changing the approved plugging program.
- 2. Plugging equipment used shall have separate mixing and displacement pumps and a calibrated tank to assure proper displacement of plugs. The Operator is responsible for providing all measuring devices needed to assure proper measurement of materials being used.
- 3. A proper tank or pit will be used to contain all fluids pumped from the well during plugging operations. Unattended pits are to be fenced.
- 4. All cement plugs are to be placed through tubing (or drillpipe) and shall be a minimum of 100 feet in length with 50% excess inside casing or 100% excess when plug is set in open hole or squeezed into perforations. 15.6%/gal slurry weight is to be used when using class B neat cement or when CaCl₂ is used. Use the recommended slurry weight of other type cements when they are used (Class C, Pozzolan etc.).
- 5. Any cement plugs placed when well is not full of fluid, or when well may be taking fluid, (i.e. across perfs-unless bridge plug or retainer is used, across bad csg., or fresh water formations) will be tagged (touched) after cement has set to verify proper location.
 - 5a. Testing The first plug below the surface plug shall generally be tested by either tagging the plug with the working pipe string, or pressuring to a minimum pump (surface) pressure of 1000 psig, with no more than a 10 percent drop during a 15-minute period (cased hole only). If the integrity of any other plug is questioned, it must be tested in the same manner. Also, any cement plug which is the only isolating medium for a fresh water interval or a zone containing a valuable mineral deposit should be tested by tagging with the drill string.
- 6. Mud must be placed between plugs. Plugging mud is to be made up with a minimum of 15 lbs/bbl of sodium bentonite, and a nonfermenting polymer.

 Minimum consistency of plugging mud must be 9 lbs/gal and with a minimum viscosity of 50 sec/qt. Fresh water is to be utilized for mixing mud.
- 7. Following the placement of a cement plug, the withdrawl rate for at least the length of the cement plug shall not exceed 30 ft/min, in order to minimize the contamination of the plug.

- 8. Within 30 days after plugging work is completed, file a Sundry Notice (Subsequent Report of Abandonment, Form 3160-5), in quintuplicate with Area Manager, Bureau of Land Management, 1235 La Plata Highway, Farmington, NM 87401. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. Show date well was plugged.
- 9. All permanently abandoned wells are to be marked with a regulation marker (4" pipe extending 4' above the ground line) containing the information as specified in 43 CFR 3162.6(d). Unless otherwise approved.
- 10. After plugging work is completed the surface is to be rehabilitated in accord with instructions from the Fluids Surface Management Section of the Farmington Resource Area Office.

All above are minimum requirements. The period of liability under the bond of record will not be terminated until the lease is inspected and surface work approved.

Please advise this office when the well location is ready for final inspection.

Failure to comply with the above conditions of approval may result in an assessment for noncompliance and/or a Shut-in Order being issued pursuant to 43 CFR 3163.1.

You are further advised that any instructions, orders or decisions issued by the Bureau of Land Management are subject to administrative review pursuant to 43 CFR 3165.3 and appeal pursuant to 43 CFR 3165.4 and 43 CFR 4.700.

14. Sept. 1 15.