Form approved.

-331 1963)	DEPARTMENT OF THE INTERIOR verse side)		P Dauget Dure.	Budget Bureau No. 42-R1424. 5. LEASE DESIGNATION AND SERIAL NO.	
	GEOLOGICAL SURV		Fed. Cont.		
				6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)				Jicarilla Apache	
			7. UNIT AGREEMENT NA	₹ W E	
CL GAS WELL	X OTHER		8. FARM OR LEASE NAT		
2. NAME OF OPERATOR					
Getty Oil Company				В"	
3. ADDRESS OF OPERATOR				9. WELL NO.	
Box 3360, Casper, WY 82602 LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface				10. FIELD AND POOL, OR WILDCAT	
				S. Blanco Pictured Cliffs	
				11. SEC., T., R., M., OR BLK. AND	
50' FSL &	600' FWL, Sec. 32-25N-5W		SURVEY OR AREA		
1030 101 0 000 1112, 0000 01 101 011				W	
4. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.)			12. COUNTY OR PARISH 13. STATE		
	6700' KB		Rio Arriba	NM	
	Check Appropriate Box To India	cate Nature of Notice, Report, or	Other Data		
	NOTICE OF INTENTION TO:	SUBSEC	QUENT REPORT OF:		
EST WATER SHUT-	PULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING V	WELL	
RACTURE TREAT	MULTIPLE COMPLETE	FRACTURE TREATMENT	ALTERING C.	ASING	
HOOT OR ACIDIZE	ABANDON*	SHOOTING OR ACIDIZING	ABANDONME	NT*	
EPAIR WELL	CHANGE PLANS X				
Other)		(Note: Report result Completion or Recom	ts of multiple completion pletion Report and Log for	on Well rm.)	
SCRIBE PROPOSED oproposed work. In nent to this work.	R COMPLETED OPERATIONS (Clearly state all p f well is directionally drilled, give subsurfa *	pertinent details, and give pertinent dates ace locations and measured and true verti-	s, including estimated dat cal depths for all marker	e of starting any s and zones perti-	
complete i	al application to plug bac n the Chacra and Pictured pose to plug back and comp	Cliffs formation and comm	ingle productio	n down	
1.	Set cement retainer at \pm	5900' and squeeze Gallup	Perfs at 5948'	-6064'.	
2.	Set cast-iron bridge plug at 2800', dump 50' of cement on top of plug filling up to 2750', to shut off Mesaverde formation to prevent casing leaks.				
3.	Perforate Pictured Cliffs single zone.	formation from 2655'-65	and complete	as a	
	the teregoing if true and correct	Anna Canadiata da la	and comprete	7.0	

(This space for Federal or State office use)

APPROVED BY _____CONDITIONS OF APPROVAL, IF ANY: