Form 3160-5 (Lovember 1983) (Formerly 9-331) UNITED STATES SUBMIT IN TRIPLICATE® (Other Instructions on re- verse side) BUREAU OF LAND MANAGEMENT	Form approved. Budget Bureau No. 1004—0135 Expires August 31, 1985 5. LEASE DESIGNATION AND SERIAL NO. SF-079600
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR FERMIT—" for such proposals.)	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
OIL GAS OTHER	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR	8. FARM OR LEASE NAME
Texaco, Inc. (505)325-4397	C.W. Roberts
3300 N. Butler, Farmington, NM 87401	9. WELL NO. #2
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface	10. FIELD AND POOL, OR WILDCAT Basin Fruitland
1650' FSL and 990' FWL of Sec. 18	11. SEC., T., B., M., OR BLK. AND SURVEY OR ARMA
	L-Sec 18- T25N-R3W
14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.) 7097 KB, 7091 GL	12. COUNTY OR PARISH 13. STATE RIO Arriba NM
16 Ct 1 A	
TEST WATER SHUT-OFF PULL OR ALTER CASING WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE ABANDON* SHOOTING OR ACIDIZING REPAIR WELL CHANGE PLANS (Other)	ALTERING CASING ABANDONMENT* f multiple completion on Well on Report and Log form.)
Texaco Producing Inc. proposes the following workover Basin Fruitland formation. The following procedure w 1. MIRUSU. Install BOP w/pipes and blind rams. 2. RIH w/cement retainer on 2-3/8" workstring and se 3. Establish injection rate and squeeze Pictured Clilow fluid loss cmt. Pull up and spot 2 sks on to Reverse out excess cmt. POH. Test casing to 500 4. RIH w/ wireline and run GR/CNL. 5. Perforate the Basin Fruitland formation with 2 JS be picked after logging. 6. RIH w/treating packer and SN and acidize w/200 ga acid per foot of pay. Flush w/fresh water to bot 7. Flow/swab back load. Test well. 8. If frac job is necessary, kill well and pull prod 9. Frac w/60,000 gal x-link carrying 192,500 lbs 20/ Immediately flush back to release pressure and cl 10. Release packer and reverse out frac sand. POH w/ 11. RIH w/production equipment and test.	ill be followed: t @ 3540'. ffs w/150 sks of p of retainer. PSIA. PF. Intervals to 1. 7.5% HCl, NEFe tom perf. uction tbg. 40 Brady sand. ose frac.