

6-20-61

F.Loc. 1005/N;1750/W

Elev. 7000 LL Spd. 6-2-6 Comp. 7-8-61 TD 7538 PB 7500

Casing S. 5 1/2 @ 506 W 525 Sx. Int. @ W Sx. Pr. 4 1/2 @ 7538 W 800 Sx. T. 2 3/8 @ 7435
Csg. Perf. Prod. Stim. T

7426-12 SLF
673 60-5
BOB
I.P. 673 MCF/D After 5 Hrs. SICP 1986 PSI After 50 Days GOR Grav. 1st Del. 26 12

TOPS		X		Well Log	TEST			DATA			
Kirtland		C-102		Plat	Schd.	PC	Q	PW	PD	D	Ref. No.
Fruitland		C-103	✓	Electric Log							
Pictured Cliffs	5126	C-104	✓	C-110							
Cliff House			3-27-62	C-122							
Menefee	4872	Ditr		Dfa							
Point Lookout		Datr		Dac							
Mancos	700	Remarks									
Gallup	1446	NITPA A Dpt. 4-25-80				3/10/67	944	40	556	472	44
Sanostee	7030	zone abandoned 4-26-80				3/4/68	829	35	532	415	42
Greenhorn	7046					6/11/69	756	32	519	378	42
Dakota	7042					5/5/70	641	45	319	321	45
Morrison						7/19/71	581	31	274	291	30
Entrada						6/19/72	556	21	245	278	20
						Disconnect 6-1-81					

Basin Dak Co. RA S 15 T 25N R 5W U C Oper. AMOCO PROD. CO. Lse. Jicarilla Cont 148 No. 13