

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

| | | |
|--|--|---|
| 1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER | | 5. LEASE DESIGNATION AND SERIAL NO. SF 079177 |
| 2. NAME OF OPERATOR Merriion & Bayless | | 6. IF INDIAN, ALLOTTEE OR TRIBE NAME |
| 3. ADDRESS OF OPERATOR Box 1541 Farmington, New Mexico | | 7. UNIT AGREEMENT NAME Canyon Largo |
| 4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1820' FSL & 810' FEL 9-25-6 | | 8. FARM OR LEASE NAME Will |
| 14. PERMIT NO. | | 9. WELL NO. 1 |
| 15. ELEVATIONS (Show whether DF, RT, GR, etc.) 6534 gl | | 10. FIELD AND POOL, OR WILDCAT Undesig Chacra |
| | | 11. SEC. T., R., M., OR BLK. AND SURVEY OR AREA 9-25-6 |
| | | 12. COUNTY OR PARISH Rio Arriba |
| | | 13. STATE New Mex |

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

X

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*


Will plug and abaondon well in following manner

Cement plug 3450 to TD

Cement plug over casing stub at approximately 2100' and cement
from 1800 to 1900 feet
Mud to 25' down in surge pipe

Cement from 25' to surface

Place 4" marker pipe and clean up location



18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

DATE 10-2-67

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY: