Form 3160-5 November 1983) Formerly 9-331)	UNITED STATES DEPARTMENT OF THE INTERIOUS BUREAU OF LAND MANAGEMENT	SUBMIT IN TRIPLICATE® (Other instructions on re-	Form approved. Budget Bureau No. 1004—013: Expires August 31, 1985 5. LEASE DESIGNATION AND SERIAL NO.
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for suca proposals.)			Jic. Cont. LS #65 8. IF INDIAN. ALLOTTES OR TRIBE NAME Jicarilla Apache
OIL GAS WELL	X OTHER		7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR Meridian	Oil Tra		8. FARM OR LEASE NAME
MCTIGIAN			Jicarilla C
P. O. Box	4289, Farmington, NM 87499-4289)	12
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface			10. FIELD AND POOL, OR WILDCAT
	0'S, 1780'E		S. Blanco Pic Cliffs 11. BRC. T. R. M. OB BL. AND Sec 16, T-25-N, R-4-W N.M.P.M.
1. PERMIT NO.	15. ELEVATIONS (Show whether of, R	T, GR, etc.)	12. COUNTY OR PARISM 18. STATE
	7159' GL		Rio Arriba NM
FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL (Other)	MULTIPLE COMPLETE ABANDON® X CHANGE PLANS	FRACTURE TREATMENT SHOOTING OR ACIDIZING (Other) (NOTE: Report results of	ABAMDONMENT*
Hene to this work.	completed operations (Clearly state all pertinent of well is directionally drilled, give subsurface location to repair the casing failure in	tetalis. and give pertinent dates. is and measured and true vertical	ction Report and Log form.) nciuding estimated date of starting any depths for all markers and some perti-
ell as needed. erf's. Tih W/p harge across co p new joint and	Nd Wellhead, NU bop. Release Paacker and test sand plug to 1000 ollar 1 joint below failure. Und screw back into production castrogen. Tih w/1 1/4" tbg & reset	acker & TOOH. Set san psi. Locate hole in ascrew casing and pul	d plug across casing. Shoot l out of hole. Pick 1000 psi.colean out d release rig.
		PEB22 1990	
		OIL CON. DIV.)	
			Angrains 9 11 0