

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL <input type="checkbox"/> GAS <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator Jerome P. McHugh		8. Farm or Lease Name Claus
3. Address of Operator P O Box 208, Farmington, NM 87499		9. Well No. 1
4. Location of Well UNIT LETTER <u>E</u> <u>1850</u> FEET FROM THE <u>North</u> LINE AND <u>790</u> FEET FROM THE <u>West</u> LINE, SECTION <u>33</u> TOWNSHIP <u>25N</u> RANGE <u>2W</u> NMPM.		10. Field and Pool, or Wildcat Undes. Nacimiento
15. Elevation (Show whether DF, RT, GR, etc.) 7205' GL; RKB = GL		12. County Rio Arriba


16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plugged and abandoned well 12-31-81; surface restoration in spring of 1982.

1. Spotted 200' bottom plug from 2297-2497' using 30 sx cement.
2. Spotted 100' plug from 1550-1650' using 15 sx cement.
3. Spotted 100' plug from 50-150' using 15 sx cement.
4. Installed dry hole marker with surface plug of 5 sx of cement.
5. Filled and leveled all pits.
6. Location cleared and cleaned of all junk.
7. Cut dead man wires.

Location ready for inspection.



18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Sherman E. Dugan Sherman E. Dugan TITLE Agent DATE 10-27-82APPROVED BY _____ TITLE DEPUTY OIL & GAS DIV. CHIEF DATE 11

CONDITIONS OF APPROVAL, IF ANY: