

NUMBER OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S	
LAND OFFICE	
TRANSPORTER	OIL
	GAS
PRODUCTION OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

FORM C-103
(Rev 3-55)

MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

Name of Company V. R. JACKSON				Address P. O. BOX 147, LONGVIEW, TEXAS			
Lease FEDERAL	Well No. 2	Unit Letter	Section 15	Township 24N	Range 2W		
Date Work Performed 7-20-61	Pool DIST. LOWER GALLUP			County SAN JUAN			

THIS IS A REPORT OF: (Check appropriate block)

- ☐ Beginning Drilling Operations
 ☐ Casing Test and Cement Job
 ☐ Other (Explain):
☒ Plugging
 ☐ Remedial Work

Detailed account of work done, nature and quantity of materials used, and results obtained.

The following cement plugs were run by Halliburton Cementing Company

150 sacks of cement placed as follows:


First plug 5340' - 5250'

Second plug 3600' - 3500'

Third plug 2500' - 2400'

Fourth plug 1700' - 1600'

Plug at surface - 10 sacks cement.



Witnessed by LEE KILLINGSWORTH	Position SUPERINTENDENT	Company SOUTH STATES DRILL. CO.
--	-----------------------------------	---

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

ORIGINAL WELL DATA

D F Elev. 6821 C. L.	T D 5340'	P B T D	Producing Interval NONE	Completion Date
Tubing Diameter	Tubing Depth	Oil String Diameter	Oil String Depth	
Perforated Interval(s)				
Open Hole Interval		Producing Formation(s)		

RESULTS OF WORKOVER

Test	Date of Test	Oil Production BPD	Gas Production MCFPD	Water Production BPD	GOR Cubic feet/Bbl	Gas Well Potential MCFPD
Before Workover						
After Workover						

OIL CONSERVATION COMMISSION

I hereby certify that the information given above is true and complete to the best of my knowledge.

Approved by Original Signed Emery C. Arnold	Name <i>Emery C. Arnold</i>
Title Supervisor Dist. # 3	Position SOUTH STATES DRILLING COMPANY
Date 7-20-61	Company

The image is a severely degraded, high-contrast black and white scan of a document. It features a large, dark, irregular shape in the upper right quadrant, which could be a stamp or a large mark. Below this, there is a grid-like structure with horizontal and vertical lines, resembling a table or a form. The text is mostly illegible due to the poor quality of the scan.