

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPPLICATE*
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	5. LEASE DESIGNATION AND SERIAL NO. NM-0557389
2. NAME OF OPERATOR Harry L. Bigbee	6. IF INDIAN, ALLOTTEE OR TRIBE NAME X
3. ADDRESS OF OPERATOR P.O. Box 669, Santa Fe, New Mexico 87501	7. UNIT AGREEMENT NAME X
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 2310' FNL and 1980 FWL Sec. 12 - TWP. 24N Rge 8W	8. FARM OR LEASE NAME Nancy
14. PERMIT NO.	9. WELL NO. # 4
15. ELEVATIONS (Show whether DF, RT, GR, etc.) GL 7287	10. FIELD AND POOL, OR WILDCAT Wildcat
	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 12-24N-8W
	12. COUNTY OR PARISH 13. STATE

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☒ABANDON* ☐CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Set Model N Packer at 6230. Perforate 6174 to 6188. Spotted 500 gallons 15% acid overnight. Water sand fracked with 10,000 lbs of 20-40 sand using 24,000 gallons of water. Drilled plugs at 6230 and at 6950 and swabbed well in. Put well back on pump. Pump quit. Pulled well, put 500 gallons of 15% MCA and swabbed acid back, set plugs at 7066 and 7063. Put in 4200 gallons of 15% MCA and swabbed well back. Put on pump jack.



RECEIVED

OCT 13 1968

U. S. GEOLOGICAL SURVEY
CARBONATE, N.

18. I hereby certify that the foregoing is true and correct

SIGNED J. A. FlintTITLE SuperintendentDATE 10/11/68

(This space for Federal or State office use)

APPROVED BY _____

TITLE _____

DATE _____

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side