

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

14-20-0603-9580

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

Navajo

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Navajo "L"

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Wildcat

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec 28, T24N, R20W

12. COUNTY OR PARISH 13. STATE

San Juan N. Mex.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL GAS WELL OTHER Dry

2. NAME OF OPERATOR
Kerr-McGee Corporation

3. ADDRESS OF OPERATOR
P. O. Box 250, Amarillo, Texas 79105

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

980' FSL & 1770' FWL, Sec 28, T24N, R20W

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

9114 GR

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT*


(Other)

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Well was never completed. 5 1/2" OD, 15.5#, J-55 ST&C casing was set at 3945' w/200 sxs 50-50 Pozmix Cement w/4% gel, and operations suspended. Casing was never perforated. Well is located on a non-producing lease that expired 3-29-71. Plugging requested to allow removal of material from lease.

Propose to shoot off pipe as deep as possible and pull same. (1) Set 150' plug (45 sxs) 50' in and 100' above csg. stub. (2) Set 75 sx plug 1250 - 1450 across base of surface pipe. (3) Set 10 sxs surface plug and install surface marker.



18. I hereby certify that the foregoing is true and correct

SIGNED

[Signature]

TITLE

District Manager

DATE

4/15/71

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY: