
Form 9-331 (May 1963)	UNITED STATES SUBMIT IN TRIPLICATE* DEPARTMENT OF THE INTERIOR (Other Instructions on re- verse side) GEOLOGICAL SURVEY		Form approved. Budget Bureau No. 42-R1424. 5. LEASE DESIGNATION AND SERIAL NO. NMO 554922	
	ORY NOTICES AND REPORTS orm for proposals to drill or to deepen or plug Use "APPLICATION FOR PERMIT—" for such i	back to a different reservoir	6 IF INDIAN, ALLOTTEE OR	TRIBE NAME
OIL GAS GTHER Dry Hole			7. UNIT AGREEMENT NAME	
WELL WELL OTHER Dry Hole 2. NAME OF OPERATOR			8. FARM OR LEASE NAME	
Tesoro Petroleum Corporation			El Dropo	
3. ADDRESS OF OPERATOR			9. WELL: NO.	
1776 Lincoln St. , Suite 1012, Denver, Colorado 80203			1	
4. Location of WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface			10. FIELD AND POOL, OR WILDCAT Wildcat	
800' FNL & 800' FEL (NE/4; NE/4)			11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA	
			Sec. 23, T24N,	R10W
14. PERMIT No. 15. ELEVATIONS (Show whether DE		of. Rt, GR, etc.)	12. COUNTY ON PARISH 13. STATE	
	6889' GL & 6901'	KB	San Juan 1	<u>New Me</u> xic
16.	Check Appropriate Box To Indicate I	Natur <mark>e of Notice, Report, or O</mark>	ther Data	
No.	NOTICE OF INTENTION TO: SUBSEQU		UENT REPORT OF:	
proposed work. If	COMPLETED OPERATIONS (Clearly state all pertine well is directionally drilled, give subsurface loc	Completion or Recomple	REPAIRING WELL ALTERING CASIN ABANDONMENT* Plug of multiple completion on Vetton Report and Log form.) including estimated date of I depths for all markers and	Well
nent to this work.) *	1 111 day the Debute ID! see	a and incomplination	madical margina	
	drilled to the Dakota 'D' zor			
	oil or gas rate from any of t			
plugged and	d abandoned this well accord	ning to the following pr	rocedure:	V

- 1. 57 sx. cement from 5950' to 6150'.
- 2. 57 sx. cement from 4900' to 5100'.
- 3. 57 sx. cement from 4000' to 4200'.
- 4. 57 sx. cement from 2150' to 2350'.
- 5. 57 sx. cement from 1450' to 1650'.
- 6. 57 sx. cement from 770' to 970'.
- 7. 15 sx. cement at surface.
- 8. A dry hole marker was installed as required by state regulations.
- 9. Location will be cleaned up and restored to the original condition and should be ready for inspection by January 15, 1975.



SEP 1 0 1976

*See Instructions on Reverse Side