DISTRICT 1 P.O. Box 1980, Hobbs, NM 88240

חוקדאורד וו

OIL CONSERVATION DIVISION

P.O. Box 2088 Santa Fe, New Mexico 87504-2088

and the second s		
ELL ÁPI NO.		
ELL ÁPI NO. 80 - 045-27740		
Indicate Type of I	esse	
,	STATE	FEE 📙

P.O. Drawer DD, Artesia, NM \$8210	5/ Indicate Type of Lease STATE X FEE
DISTRICT III 1000 Rio Brazos Rd., Aziec, NM 87410	6. State Oil & Gas Lease No. LG-8804
SUNDRY NOTICES AND REPORTS ON WELLS	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OF DIFFERENT RESERVOIR. USE "APPLICATION FOR PERM (FORM C-101) FOR SUCH PROPOSALS.)	7. Lease Name or Unit Agreement Name
1. Type of Well: OIL GAS WELL X WELL OTHER P & A	Muppet
2. Name of Operator DUGAN PRODUCTION CORP.	8. Well No.
3. Address of Operator	9. Pool name or Wildcat
P.O. BOX 420, FARMINGTON, NM 87499	Undesignated Gallup
4. Well Location	000
Unit Letter M: 330 Feet From The SOUTH	Line and 990 Feet From The WEST Line
Section 2 Township 24 N Range	
10. Elevation (Show whether DF)	GR ////////////////////////////////////
11. Check Appropriate Box to Indicate Na	ture of Notice, Report, or Other Data
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON X	REMEDIAL WORK ALTERING CASING
TEMPORARILY ABANDON CHANGE PLANS C	COMMENCE DRILLING OPNS. DUG AND ABANDONMENT
PULL OR ALTER CASING C	CASING TEST AND CEMENT JOB
OTHER:	OTHER:

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

SEE ATTACHED FOR PROPOSED PLUGGING PROCEDURE.

SEP 2 0 1990
OIL CON. DIV.

(This space for State Use) Original Signed by CHARLES GHOLSON DEPUTY CHL & GAS INSPECTOR, DIST. #3	
/ 1 / / 1	TELEPHONE NO. 325-1821
SKONATURE Just Geologist	DATE 9-19-90
I hereby certify that the information above is true and complete to the best of my knowledge and belief.	

CONDITIONS OF APPROVAL, IF ANY:

Attachment to NMOCD Form C-103
Notice of Intention to Plug & Abandon
Dugan Production Corp.
Muppet #3
M-2-24N-11W
September 19, 1990

Plan to Plug & Abandon Well as follows:

- 1. Spot 100' cement plug across top of Gallup Formation 4790-4690'.
- 2. Spot 100' cement plug across base of Mesaverde Formation 3988'-3888'.
- 3. Spot 100' cement plug across top of Mesaverde Formation 2110-2010'.
- 4. Spot 100' cement plug across top of Pictured Cliffs Formation 1385-1285'.
- 5. Spot 100' cement plug across top of Fruitland Formation 1205' 1105'
- 6. Spot 100' cement plug base of Ojo Alamo Formation 585-485'.
- 7. Spot 100' cement plug 50' inside and 50' outside 8-5/8" surface casing.
- 8. Spot surface plug and install dry hole marker.
- 9. Restore surface location.

*Note: This well was drilled to T.D. of 5110'. T.D. was reached on 9-17-90. After logging well it was decided to plug and abandon and verbal communication with Mr. Charles Gholson N.M.O.C.D. Aztec office conveyed these plans.