

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR <u>Kimbell Oil Company of Texas</u> <i>Curtis J. Little</i>	8. FARM OR LEASE NAME <u>Warren Fed</u>
3. ADDRESS OF OPERATOR <u>P.O. Box 1097, Farmington, New Mexico 87499</u>	9. WELL NO. <u>B</u>
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface <u>990' FSL and 990' FEL - Sec. 26, 25N, 6W</u>	10. FIELD AND POOL, OR WILDCAT <u>Basin Dakota</u>
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.) <u>6670 GL</u>
	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA <u>Sec. 26, T25N, R6W</u>
	12. COUNTY OR PARISH <u>Rio Arriba</u>
	13. STATE <u>NM</u>

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF	<input type="checkbox"/>	PULL OR ALTER CASING	<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>	MULTIPLE COMPLETE	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>	ABANDON*	<input checked="" type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>	CHANGE PLANS	<input type="checkbox"/>
(Other)	<input type="checkbox"/>		<input type="checkbox"/>

SUBSEQUENT REPORT OF:

WATER SHUT-OFF	<input type="checkbox"/>	REPAIRING WELL	<input type="checkbox"/>
FRACTURE TREATMENT	<input type="checkbox"/>	ALTERING CASING	<input type="checkbox"/>
SHOOTING OR ACIDIZING	<input type="checkbox"/>	ABANDONMENT*	<input type="checkbox"/>
(Other)	<input type="checkbox"/>		<input type="checkbox"/>

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. pull out of hole and tally tubing
2. TIH and circulate well clean
3. spot cement plugs - PB depth of 7005' to 50' above the top of the Greenhorn
100' across each of the formation tops; Gallup
Mesaverde
Chacra
Pictured Cliffs
Ojo Alamo
4. perforate squeeze hole at 50' below surface casing shoe, squeeze cement thru
holes and leave production casing full
5. cut off wellhead and install P & A marker
6. remove all surface production equipment and tank, remove pit fence and fill
in pit
7. rehabilitate surface/ reseed as per BLM instructions
8. plugging will begin after approval

18. I hereby certify that the foregoing is true and correct

SIGNED Susan Little

TITLE Production Superintendent

DATE 10/24/87

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

OCT 29 1987
DATE 10/24/87

FARM

*See Instructions on Reverse Side
NMOCC

BUREAU OF LAND MANAGEMENT
CALLER SERVICE 4104
FARMINGTON, NEW MEXICO 87499

Attachement of Notice of
Intention to Abandon

Re: Permanent Abandonment

Well: 3 Warren

CONDITIONS OF APPROVAL

1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal Leases."
2. The Farmington Office, telephone (505) 325-4572, is to be notified in sufficient time for a representative to witness all plugging operations.
3. Blowout prevention equipment is required.
4. The following modifications to your plugging program are to be made (when applicable):

Gallup 5875'	plug 5925' - 5825'	inside & outside	9 1/2" casing perfor 5925'
Mesa Verde 4090'	" 4140' - 4040'	" "	" " perfor 4140'
Chaco 3400	" 3450 - 3350'	" "	" " perfor 3450'
Pictured Cliffs 2545'	" 2595' - 2495'	inside	9 1/2" casing
Franchel 2355'	" 2405' - 2305'	" "	" "
Ojo Alamo Base 2165'	" 2215' - 2115'	" "	" "
top 2050'	" 2100' - 2000'	inside & outside	9 1/2" casing perfor 2100'

Office Hours: 7:45 A.M. to 4:30 P.M.