UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELDSUM (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT" for such proposals) 3:00	5. Lease NMNM-03733 6. If Indian, Allottee or Tribe Name 7. Unit Agreement Name
1. Oil Well [] Gas Well [] (008 Hern NOTON, NM GAS WELL	8. Well Name and No. BREECH 224
2. Name of Operator:	9. API Well No.
Caulkins Oil Company	30-039-06508-00Q2
3. Address of Operator: (505) 632-1544 P.O. Box 340, Bloomfield, NM 87413	10. Field and Fool, Exploratory Area GREENHORN, MESA VERDE, CHACRA, PICTURED CLIFF
4. Location of Well (Pootage, Sec., Twp., Rge.)	ll. Country or Parish, State
865' F/N 1140' F/E, SEC. 13-26N-7W	Rio Arriba Co., New Mexico
12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA	
TYPE OF SUBMISSION TYPE OF ACTION	
[] Notice of Intended CERVE Abandonment [X] Subsequent Report OCI - 2 1995 [] Plugging Back [] Pinal Abandonment OCI - 2 1995 [] Pinal Abandonment Recompletion [] Plugging Back [] Casing Repair [] Abandonment Recompletion [] Plugging Back [] Casing Repair [] Abandonment [] Plugging Back [] Abandonment [] Plugging Back [] Casing Repair [] Abandonment [] Plugging Back [] Abandonment [] Abandonment [] Plugging Back [] Abandonment [] A	[] Change of Plans [] New Construction [] Non-Routine Practuring [] Water Shut-Off [] Conversion to Injection [] Dispose Water
17. Describe Proposed or Completed Operations:	
9/6/95 Pulled tubing with packer and reverse flow check valve, inspecting for hole in tubing.	
No hole was found in tubing. Installed new dual wellhead.	
Re-ran 2 3/8" tubing and landed on doughnut at 7611' with 7" Baker R-3 packer set at 4635' for Greenhorn - Mesa Verde production.	
Ran 1 1/2" tubing and landed at 2885' for Otero Chacra - Pictured Cliff production.	
NOTE: It was determined that we were logging off production form the Greenhorn and Mesa Verde zones through the reverse flow check valve installed above packer. To remedy this problem it was decided to dual complete the Greenhorn - Mesa Verde below a packer and the Otero Chacra - Pictured Cliff above packer. Well is now surface commingled in all four zones at the surface.	
NOTE: The format is issued in lieu of U.S. BLM Form 3160-5	
18. I HEREBY CERTIFY THE FOREGOING IS TRUE AND CORRECT SIGNED: Robert 1 Vergee TITLE: Superintendent DATE: 09/21/95	
ROBERT L. VERQUER ACCEPTED FOR RECORD	
APPROVED BY:TITLE:	SEP 2 7 1995:
CONDITIONS OF APPROVAL, IF ANY	FARMINGTON DISTRICT OFFICE
DI	

....

.

.

The first of the second of the

Spirit Comment

The state of the s