Form 3160-5 (November 1983) (Formerly 9-331)	UNITED STATES DEPARTMENT OF THE I BUREAU OF LAND MANAGE	NTERIOR verse side)	5. LEASE DESIGNATION AND SHELL NO Jicarilla Contract 107
SUN (Do not use this	dicarilla Apache		
1.		/	7. UNIT AGREEMENT NAME
OIL GAS X OTHER			N/A
2. NAME OF OPERATOR			S. FARM OR LEASE NAME
Union Texas Petroleum			JICARILLA F
3. ADDRESS OF OPERATOR	9. WELL HO.		
375 U.S. Hig	6		
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1820' FSL & 1010' FWL			Blanco Mesaverde 11. SBC, T, E, M., OR BLE. AND
1820° F	2F % 1010. LMF	FAN 1.2 1387	Section 34-T26N-R4W
14. PERMIT NO.	15 ELEVATIONS (Show	whether of the GR. etc.)	12. COUNTY OR PARISH 13. STATS
14. Parsiti No.	6874 KB	FARMINGTON RESOURCE AREA	Rio Arriba NM
16.	Check Appropriate Box To In	dicate Nature of Notice, Report, or (Other Data
	URNT REPORT OF:		
TEST WATER SEUT-O FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL	PULL OR ALTER CASING MULTIPLE COMPLETE ABANDON® CHANGE PLANS		REPAIRING WELL ALTERING CASING ABANDONMENT* ne Abandonment XX s of multiple completion on Well
(Other)		Completion or Recomp	pletion Report and Log form.)
union Texas P	•	se that the Pictured Cliffs and one as follows:	
2. Set RBP @ All teste 3. Set RBP @ 4. Squeeze P CaCl2. S 5. Drill out 6. Remove RB	ed to 1500 psi - held Ok. 9 3591'. Set pkr @ 3451' PC perfs (3493'-3507') wi Squeeze to 1200 psi. c cement and test squeeze	t. Swab test PC perfs. Te ith 100 sxs (118 cu.ft.) Cl e to 800 psi - held OK.	sted wet.
		्रा ।	

SMM