

J

30-039-22062

5-10-79

7420

7898

F. Loc. 1820/S; 1010/W

Elev. 6863

Spd. 10-22-79

Comp. 40-3-80 TD 7910

PB 7898

Casing S. 8 5/8 @ 271 W 180 Sx.

Int.

@

W

Sx. Pr. 5 1/2 @ 7910

W 550

Sx.

I. 2 1/4 @ 3504

Csg. Perf.

3494-3507

Prod. Stim.

124

TRANS

I.P. 1333 BO/D MCF/D After Hrs. SICP 1042 PSI After Days GOR Grav. 1st Del. 7-1-82

TOPS		NITD	Well Log	TEST DATA							Ref.No.
Kirtland	2970 3150	C-103	Plat	Schd.	PC	Q	PW	PD	D		
Fruitland	3266	C-104 3-19-82	Electric Log	8-16-82	773	196	341	618	99	5391	
Pictured Cliffs	3432	9-24-82 1 3/4	C-122	4/24/85	641	46	417	513	31		
Cliff House	5106	Ditr 10-1-82	Dfa 7/10/82	8/8/84	889	19	407	711	10		
Menefee		Datr	Dac	Disconnection 5-10-85							
Paint Lookout	5550	PT 82 sq PC ports (3493-3507) w/ 1180 f. 82		4/19/85	629	1	290	317	1		
Mancos		zone abandonment 120-87									
Gallup	6700										
Sonotee											
Greenhorn											
Dakota	7664										
Morrison											
Entrada											

P

o

Blanco PC Co. S 34 T 26 N R 4 U L Oper Union Tx Petro Corp Loe. Jicarilla F No. 6