

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Budget Bureau No. 100J-000
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐		3. FARM OR LEASE NAME <i>Jicarilla Apache A118</i>	
2. NAME OF OPERATOR <i>Amoco Production Co.</i>		4. IF INDIAN, ALLOTTEE OR TRIBE NAME <i>Jicarilla Apache</i>	
3. ADDRESS OF OPERATOR <i>2325 East 30th St.; Farmington, NM 87401</i>		5. UNIT AGREEMENT NAME	
4. LOCATION OF WELL (Record location clearly and in accordance with any State requirements.* See also space 17 below) At surface <i>930' FSL x 1450' FWL</i>		6. WELL NO. <i>9</i>	
14. PERMIT NO. API No. <i>3003923557</i>		7. FIELD AND POOL, OR WILDCAT <i>Gits Helop - Dakota</i>	
15. ELEVATIONS (Show whether of, ft, gr, etc.) <i>7400' GL 7411</i>		8. SEC., T., R., M., OR BLK. AND SURVEY OR AREA <i>Sec 35 T26N R3W</i>	
16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data		9. COUNTY OR PARISH 13. STATE <i>Los Arriba New Mexico</i>	

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐	WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACURE TREAT ☐	MULTIPLE COMPLETION ☐	FRACURE TREATMENT ☐	ALTERING CASING ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☐	SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☒
REPAIR WELL ☐	CHANGE PLANS ☐	(Other) <i>Plug and abandon</i>	
(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)			
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting and proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)			

Service rig moved in 5-18-89 Plug from 6845-5700 ft with 27 bbls mud; spot with 30 cu ft cement. Plug from 5700-5600 ft with 37 bbl mud. Plug from 5600-4000 ft; spot with 57 bbl mud. Plug from 4000-3500 ft with 37 bbls mud. Plug from 1900-1700 ft with 31 bbl mud. Plug from 1700-306 ft pump 53 cu ft cement Plug from 306-surface. Pump 6 cu ft cement. Seal Annulus to top and dig out around wellhead. Cut off casing below bradenhead and weld on PxA marker. Clean up location and rig down and released 1000 hr 5-26-89. PxA date 5-27-89. Liding window between July 1 and Sept 15, 1989.

I hereby certify that the foregoing is true and correct

SIGNED *K.K. Stratten*

TITLE *Adm. Supervisor*

DATE *6-13-89*

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE
NMOOD

DATE

*See Instructions on Reverse Side