Form 9-331 (May 1963)

16.

## UNITED STATES DEPARTMENT OF THE INTERIOR (Other interior verse side)

SUBMIT IN TRIPLICATE\*
(Other instructions on re-

Form approved. Budget Bureau No. 42-K1424. 5. LEASE DESIGNATION AND SERIAL NO.

	6. IF INDIAN, ALLOTTEE OR TRIBE NAME			
SUNDRY NO	7. UNIT AGREEMENT NAME			
OIL GAS GAS THE	S. FARM OR LEASE NAME			
2. NAME OF OPERATOR Shelly Oil Company	9. WELL NO.			
3. ADDRESS OF OPERATOR 1860 Lincoln Stree	10. FIELD AND POOL, OR WILDCAT			
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*  See also space 17 below.)  At surface  (60.* F3L & 1980* F8L		Last Older Callog  11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA		
14. PERMIT NO.	15. ELEVATIONS (Show whether DP, RT, GR, etc.)	33=25H-1Ch 12. COUNTY OF PARISE 13. STATE 53/1 JUST R. M.		
The state of the s				

## Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:			SUBSEQUENT REPORT OF:					
							REPAIRING WELL	
TEST WATER SHUT-OFF	1	PULL OR ALTER CASING		1	WATER SHUT-OFF		1.1-	
		MULTIPLE COMPLETE	Ga.1.	1.104	FRACTURE TREATMENT		ALTERING CASING	-
FRACTURE TREAT			1 mm - 1		SHOOTING OR ACIDIZING	1 197	ABANDONMENT*	
SHOOT OR ACIDIZE	<u>  </u>	ABANDON*		<b>'</b> F'	SHOOTING OR ACIDIAM			1
REPAIR WELL		CHANGE PLANS			(Other) (Note: Report_res	sults of multiple	completion on We	ell
(Other) Converti	wates	r well		i	Completion or Rec	ompletion Repor	t and nog rorm.)	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent. Well ko. 79 has watered out from autorflood operations and has no further usefulness to the unit in its present some of completion. Therefore, we propose to convert the well to test and evaluate the Ojo Alago inverval as a supplemental water supplu source.

Car plan is as follows:

1. Move in and rig up pulling unit.

2. Pull rods and tubing and reman tubing open ended.

Abandon Gallup by spotting a sack plug from 5398 to 5178.

Pull tobing.

5. Perforate with 4 holes at 1100% for coment job across 0jo Alamo.

6. Cement with 200 sacks. WOC 12 hours.

Perforate with 2 holes per feet 850-900" and 915-925" (total 120 holes).

swab and/or bail to clean up for production test. ပ်နှ

hun 21/8" OD tubing, pump and rods. 9.

