May 1963;	UNITED STATES SUBMIT IN TRIPLICATES  DEPARTMENT OF THE INTERIOR (Other instructions on red) GEOLOGICAL SURVEY		5. LEASE DESIGNATION AND SERIAL NO. L. M. Phillips No. 3		
(Do not use this	DRY NOTICES AND form for proposals to drill or Use "APPLICATION FOR PEI	REPORTS OF the deepen or plug back	N WELLS k to a different reservoir.	6. IF INDIAN, ALLOTTEE OR THE	BE NAMI
I. OIL GAS				7. UNIT AGREEMENT NAME	
well well other Fresh Water Source 2. NAME OF OPERATOR			Carson Unit 8. FARM OR LEASE NAME		
Shell Oil Comp	pany	····		G. FARM OR BEASE NAME	
1700 Broadway, Denver, Colorado 80290  4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*  See also space 17 below.)  At surface				9. WELL NO.  2-25  10. FIELD AND POOL, OR WILDCAT	
660' FNL & 327.43' FWL Section 25				Bisti 11. sec., T., R. M., OR BLK. AND SURVEY OR AREA Section 25-T25N-R12W	
14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.)		GR, etc.)	12. COUNTY OF PARISH 13. ST.	ATE	
	64	430 KB		San Juan N.I	М
i.	Check Appropriate Box	k To Indicate Nat	ure of Notice, Report, or C	Other Data	
,	OTICE OF INTENTION TO:	1		UENT REPORT OF:	
TEST WATER SHUT-OF	F PULL OR ALTER 6	ASING	WATER SHUT-OFF	REPAIRING WELL	
FRACTURE TREAT	MULTIPLE COMPI	ETE	FRACTURE TREATMENT	ALTERING CASING	
SHOOT OR ACIDIZE	ABANDON*		SHOOTING OR ACIDIZING	ABANDONMENT*	x
REPAIR WELL	CHANGE PLANS		(Other)		
(Other)			Completion or Recompl	of multiple completion on Well letion Report and Log form.) including estimated date of star	
	Se	e attachment			
	L SUNDRY WHEN LOCAT ADY FOR INSPECTION	ION			
	_				
I hereby certify that t	he foregoing is true and correc	t			

cc: NMO&GCC

APPROVED BY \_\_\_\_\_CONDITIONS OF APPROVAL, IF ANY:

DATE \_\_\_

TITLE \_\_

WELL P&A BISTI SHELL OIL COMPANY CARSON UNIT LEASE WELL NO. 2-25 DIVISION WESTERN 6430 KB ELEV FROM: 10/12/77 COUNTY SAN JUAN STATE NEW MEXICO

NEW MEXICO BISTI FIELD Carson Unit 2-25 (P&A)

"FR" TD 5000. PB 3888. AFE #570776 provides funds to plug & abandon well. 10/3 RU Bedford. Pulled 20 jts 2-3/8 tbg. 10/4 Fin'd pull'g tbg & BJ pmp. Ran workstring to PBTD. 10/5 Circ'd well w/gel. Spt'd 140 sx cmt plug over & across Allison Menefee perfs. Pulled workstring out of well. Set jacks. 10/7 Perf'd csg @ 1151'. Ran tbg. Spt'd 50 sx cmt plug over Pictured Cliffs & Fruitland Coal. Pulled tbg to 400'. Displ'd 20 sx cmt thru perfs @ 1151'. Pulled tbg out of hole. Placed 10 sx cmt plug on sfc. Set abandonment marker & RD Bedford. OCT 12 1977 FINAL REPORT