17 X

(SUBMIT IN TRIPLICATE)

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

	Bureau No. 42-1	R358.4.			
	-				
and Offic	Santa Fe	, Nelle			
.ease No.	SF-078061				
Jnit	Carson				
J334					

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	L	SUBSEQUENT REPO	ORT OF WATER SHUT-OFF	
		RT OF SHOOTING OR ACIDIZING.		
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPO	ORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-D	RILL OR REPAIR WELL	SUBSEQUENT REPO	RT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOO	OT OR ACIDIZE	SUBSEQUENT REPO	RT OF ABANDONMENT	
IOTICE OF INTENTION TO PULL	OR ALTER CASING	SUPPLEMENTARY \	WELL HISTORY	
NOTICE OF INTENTION TO ABAN	IDON WELL	·y		
		<u> </u>		
(IN	IDICATE ABOVE BY CHECK MARK	NATURE OF REPORT, NO	TICE, OR OTHER DATA)	
		June 18		, 19.63
		S line and	942 ft. from $\left\{\begin{array}{c} E \\ W \end{array}\right\}$ line o	f sec. 17
SE/4 17 (½ Sec. and Sec. No.)	25H		(Meridian)	
Bisti	San J		New Mexico	
(Field)		r Subdivision)	(State or Territory)	
4909-17, 49	53-57, 4967-77, 49	ce-la brobru	1/2" @ 5028. Perf g 25 mDO, GOR 3520.	
Cohamilan doubh	of fill, clean out	to 4940'. i	f required. at 4750'_, pressur	e test cas
Kun tubing with	LECLIDARUTE DETABLE	hand men and		
to 3000 psi.	tony waset bridge	plus at 4940	e and pull tubing.	
Ti fest matrerer	ing 1200 bbls. les	an emula X	000 the 20-40 sand	10.000 1
			CAC The Property and	is the contract of
Janeary and 1	ore the. finid los	is additive.		11 10
10-20 sand and 1	.000 lbs. fluid los	e SCHTITAGE	AT	MAIL
10-20 send and 1 Clean out send a	.000 lbs. fluid los bove bridge plug s	e SCHTITAGE	(136)	IVED
10-20 sand and 1	.000 lbs. fluid los bove bridge plug s	e SCHTITAGE	(136)	IVED
10-20 send and 1 Clean out send a Place on product	.000 lbs. fluid 10s bove bridge plug s ion and test.	nd retrieve.	REC	1963 00 1963
10-20 sand and 1 Clean out sand a Place on product	.000 lbs. fluid 10s bove bridge plug s ion and test.	nd retrieve.	REC	1/ED
10-20 send and 1 Clean out send a Place on product	.000 lbs. fluid 10s bove bridge plug s ion and test.	nd retrieve.	REC	1963 00 1963
10-20 send and 1 Clean out send a Place on product	.000 lbs. fluid 10s bove bridge plug s ion and test.	nd retrieve.	REC	1963 20 1963
Clean out sand a Place on product Tunderstand that this plan of the plan of t	coo lbs. Fluid 10s bove bridge plug a lon and test. of work must receive approval in Company	nd retrieve.	cal Survey before operations may	1963 20 1963
Clean out sand a Place on product Tunderstand that this plan of the plan of t	COO lbs. Fluid 10s bove bridge plug s ion and test. of work must receive approval in Company	nd retrieve.	cal Survey before operations may OIL	1/ED
Clean out sand a Place on product Tunderstand that this plan of ompany Shell oil ddress P. C. Box	coo lbs. Fluid 10s bove bridge plug a lon and test. of work must receive approval in Company	writing by the Geologic	Criginal signed by	120 1963 CONT. COM DIST. 3
Clean out sand and land clean out sand a Place on product I understand that this plan of Company Shell Oil Address P. O. Box	COO lbs. Fluid 10s bove bridge plug s ion and test. of work must receive approval in Company	writing by the Geologic	cal Survey before operations may OIL	120 1963 CONT. COM DIST. 3