Form 3160-5 (June 1990)

1. Type of Well

X Oil Well

2. Name of Operator

UNITED STATES

DEPARTMENT OF TH BUREAU OF LAND MANAC

E INTERIOR ANAGEMENT	ยอบ	_ 1	F1: 12:	39
ANAGEMENT	1.40 =			

SUNDRY NOTICES	AND	REPORTS	ON	WELLS
----------------	-----	---------	----	-------

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir

Use "APPLICATION FOR PERMIT --" for such proposals

SUBMIT IN TRIPLICATE Gas Well Other

Giant Exploration & Production Company 3. Address and Telephone No. P.O. Box 2810, Farmington, New Mexico 87499 (505)326-3325

4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 1881' FNL, 1980' FEL, Sec. 17, T25N, R11W

Carson Unit 8. Well Name and No.

Carson Unit #32-17 9. API Well No.

30-045-05413

10. Field and Pool, or Exploratory Area Bisti Lower Gallup

FORM APPROVED

Budget Bureau No. 1004-0135

6. If Indian, Allottee or Tribe Name

7. If Unit or CA. Agreement Designation

Expires: March 31, 1993 5. Lease Designation and Serial No.

SF 078062-A

11. County or Parish, State San Juan, New Mexico

 l2.	CHECK APPROPRIATE BOX(s	TO INDICATE NATURE OF NOTICE, I	REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION		
	Abandonment	Change of Plans	
X Notice of Intent	Recompletion	New Construction	
	Plugging Back	Non-Routine Fracturing	
Subsequent Report	Casing Repair	Water Shut-Off	
• •	Altering Casing	Conversion to Injection	
Final Abandonment Notice	X Other Return to Production	 (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) 	
		completion of Recompletion Report and Degreently	

13. Describe Proposed or Completed Operations (Clearly state all portinent dates, including estimated date of starting any proposed work. If well is directionaly drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Giant Exploration & Production Company intends to return the subject well to production as follows:

- 1) Clean out to well to 5028'.
- 2) Pressure test casing.
- 3) Perforate Gallup (5009'-5026') w/4 JSPF.
- 4) Acidize perforations with 1000 gal. 15% HCl.
- 5) Frac well down tubing w/25,000 gals. cross linked gel carrying 65,000# 12/20 mesh sand.
- 6) Clean out to PBD.
- 7) Install production tubing string. (Note: if casing leaks are encountered, a scab liner with isolating packers will be run across the leaking interval prior to running the production string.)
- 8) Return well to production.

14. I hereby certify that the foregoing is true and correct NOV 0 3 1994 TitleArea Engineer Paul R. Williams (This space for Federal or State office use) Date Approved by Conditions of aproval, if any:

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictious or fraudulent statements or representations as to any maner within its jurisdiction.

*See Instruction on Reverse Side

APPROVEU