Form 9-331 (May 1963)	11:11-		
DEPAE	UNITED STATI RTMENT OF THE		re- Budget Bureau No. 42-R1424.
	GEOLOGICAL SU		5. LEASE DESIGNATION AND SERIAL NO.
SUNDRY NO	OTICES AND REP	PORTE ON WITH SO	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
(Do not use this form for pr Use "APP"	roposals to drill or to deep LICATION FOR PERMIT—	en or pure med to a different reservoir. "for such a cosaisa	
OIL GAS WELL OTHER			7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR			West Bisti Unit 8. FARM OR LEASE NAME
Gulf Oil Corporat	tion		
P. O. Box 670, Hobbs, NM 88240			9. WELL NO.
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*  See also space 17 below.)  At surface			10. FIELD AND FOOL, OR WILDCAT
660' FNL & 660' FWL			Bisti Lower Gallup
	2.172		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
14. PERMIT NO.	15. ELEVATIONS (Show	w whether DF, MF, GR, etc.)	Sec 12-T25N-R13W
	l .	6256 GL	San Juan NM
16. Check	Appropriate Box To I	ndicate Nature of Notice, Report, o	
	STENTION TO:		EQUENT REPORT OF:
TEST WATER SHUT-OFF	PULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING WELL
FRACTURE TREAT	MULTIPLE COMPLETE	FRACTURE TREATMENT	ALTERING CASING
REPAIR WELL	ABANDON*	SHOOTING OR ACIDIZING	ABANDONMENT*
(Other) TA	CHANGE PLANS	(Other) (Note: Report resu	lts of multiple completion on Well appletion Report and Log form.)
		÷	
POH with tubing a Locate leak in ca	nd packer. Set sing. Additiona	CIBP at 4800', cap with 35	o' cement. cted.
POH with tubing a Locate leak in ca	nd packer. Set sing. Additiona	CIBP at 4800', cap with 35	o' cement. ted.
POH with tubing a Locate leak in ca	nd packer. Set sing. Additiona	CIBP at 4800', cap with 351 cap	o' cement. Eted.
POH with tubing a Locate leak in ca	nd packer. Set sing. Additiona	CIBP at 4800', cap with 35	o' cement. ted.
Locate leak in ca.	sing. Additiona	I procedure will be submit	ted.
Locate leak in ca.	sing. Additiona	I procedure will be submit	ted.
Locate leak in ca.	sing. Additiona	I procedure will be submit	ted.
Locate leak in ca.	sing. Additiona	I procedure will be submit	ted.
Locate leak in ca.	sing. Additiona	I procedure will be submit	ted.
Locate leak in ca.	sing. Additiona	I procedure will be submit	ted.
Locate leak in ca.	sing. Additiona	CIBP at 4800', cap with 35 of procedure will be submit to the operator who is or P&A'm incumstances	ted.
Locate leak in ca.	sing. Additiona	I procedure will be submit	ted.
approved nopairing	sing. Additional	I procedure will be submit	ted.
approved Repairing	Subject of the lead on the co	I procedure will be submit	- either  g the well,
approved  Approv	sing. Additional	to the operator will be submit to the operator which (5) or f & A/in Incumstances	ted.
approved Approved Approved Approved SIGNED PLANTER APPROVED APPROV	Sing. Additiona  Sobject of the lead on the cu  g is true and correct  Tive office use)  MOND W. VIAYARD TIV	to the operator	- either  g the well,

\*See Instructions on Reverse Side