

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPlicate*
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 42-R1424

5. LEASE DESIGNATION AND SERIAL NO.

NM 036254

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. ☐ OIL WELL ☐ GAS WELL ☐ OTHER <u>Water Injection Well</u>	7. UNIT AGREEMENT NAME <u>Central Bisti</u>
2. NAME OF OPERATOR <u>Mixon Development Co.</u>	8. FARM OR LEASE NAME <u>CBU</u>
3. ADDRESS OF OPERATOR <u>341 Milam Bldg. San Antonio TX 78205</u>	9. WELL NO. <u>W1 6</u>
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface <u>3' PNL & B15 PWN Sec 15 T25N R12W</u> <u>SAN JUAN Co., N.M. NMPM</u>	10. FIELD AND POOL OR WILDCAT <u>Bisti Gallup</u>
11. PERMIT NO.	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA <u>Sec 15, T25N R12W</u> <u>NMPM</u>
12. ELEVATIONS (Show whether DE, RE, CM, etc.) <u>6248 DF</u>	12. COUNTY OR PARISH <u>SAN JUAN</u>
	13. STATE <u>N.M.</u>

15. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING


ABANDONMENT*

(Note: Report results of multiple completion on Well Completion or Etc. Completion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

This well is no longer necessary to Unit. We intend to plug & abandon this well as follows:

1. Squeeze Perf. 4760'-4864'
2. Spot 10% plug inside Csg @ top of Pt. Look-out.
3. Cut & Pull 4 1/2" Csg.
4. Place Plug 50' inside Stub to 50' Above 5 1/2" Csg.
5. Place 150' plug over top of A
6. Set P&A Marker w/ 10% surface Plug
7. Clean Loc.



I hereby certify that the foregoing is true and correct

SIGNED

Lang G. Bedford

TITLE

Agent for Operator

DATE

June 3, 74

APPROVED BY

(Indicate position of approval, if any)

TITLE

RECEIVED

JUN 4 1974

*See Instructions on Reverse Side

U. S. GEOLOGICAL SURVEY
FARMINGTON, N. M.