Form 3160-5 (June, 1990)

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993

5. Lease Designation and Serial No.

SF 079360 SUNDRY NOTICES AND REPORTS ON WELLS 6. If Indian, Allotee or Tribe Name Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT"-for such proposals 7. If Unit or CA, Agreement Designation SUBMIT IN TRIPLICATE **RINCON UNIT** Type of Well Well Name and No Rincon #185 9. API Well No **PURE RESOURCES** 30-039-07008 Address and Telephone No P.O. BOX 850 - BLOOMFIELD, NM 87413 Location of Well (Footage, Sec., T., R., or Survey De Basin Dakota/Pictured Cliff MV "A" - 990' FNL & 990' FEL Rio Arriba, NM Sec. 22, T27N, R07W CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA 12. TYPE OF ACTION TYPE OF SUBMISSION Change of Plans П Notice of Intent Abandonment New Construction Recompletion X Non-routine Fracturing Plugging Back Subsequent Report Water Shut-Off Casing Repair Conversion to Injection Altering Casing Final Abandonment Notice Dispose Water Other Temporarily Abandonment Report results of multiple completion on Well 13. Describe Proposed of Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled give subsurface locations and measured and true vertical depth for all markers and zones pertinent to this work.)\* Pure Resources request permission to TEMPORARILY ABANDON the Basin Dakota zone and perforate and complete the Point Lookout Mesa Verde. See attached procedures 06/28/01 San Juan Basin Foreman Signed Micheal C. Phillips (This space for Federal or State office use) Conditions of approval, if any: Title AUG

Title 18 U.S.C. Sections 1001, makes is a crime for any person knowingly and willfully to make to any department or agency of the united states of false, fictitious of fraudulent state of representations as to any matter within its jurisdictions.

ASSET GROUP: PB/RM

FIELD: Rincon

LEASE/UNIT: Mesa Verde
COUNTY: Rio Arriba



DATE: BY:

Jun. 28, 2001 M.C. Phillips

**WELL: 185** 

STATE:

New Mexico

SPUD DATE: 11/10/62 COMP. DATE: 12/3/62

STATUS: Producer

KB = 6,597'
Elevation = 6,587'
TD = 7,593'
PBTD = 7,565'

## Procedure:

1. MIRU WS RIG. Blow well to pit. ND WH. NU BOP. NU spool and blooie line. Lower and check for fill. TOH tallying tubing out of hole. Also check for scale and parrafin.

- 2. PU and TIH and set ezdrill CIBP @ 7300'. TOH. PU and TIH w/ PKR on 2-7/8" WS. SPA 5000'. Pressure test casing, DV tool and CIBP to 1500#. TOH.
- 3. RU WL. RIH and perf point lookout ( perfs to be given at later date). TIH w/ packer on 2-7/8" WS. SPA 50' above top perf.
- 4. RU BJ services. Breakdown perforations. Acidize perfs and divert using 1.3 SG balls and ball off perfs. Surge balls off. Knock balls off of perfs w/ PKR if necessary. Frac new formation using 30# Linear 70Q foam, ramping sand from 2-5ppg w/flexsand added to 5# stage at 15% by volume. TAG FRAC.
- 5. Flowback well overnight. Release packer and TOH. RIH w/OE'd 2-3/8" tubing.
  Clean out well to CIBP w/ air mist. Drop ball and pump off expendable check.
  Dry well up with air. PUH and land well to 10' from btm perf. SWI for pressure build up.
  RD PU. SWI for pressure build-up. RU WL. Run dip in pressure test. Run after frac log.
- 6. Notify elpaso of pending first delivery. Put well down salesline.



