NEW MEXICO OIL CONSERVATION COMMISSION Santa Fe, New Mexico

MISCELLANEOUS NOTICES

Submit this notice in TRIPLICATE to the District Office, Oil Conservation Commission, before the work specified is to begin. A copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission.

tional instructions in the Rules and Regulations of the Commission. Indicate Nature of Notice by Checking Below Notice of Intention Notice of Intention Notice of Intention to TEMPORARILY ABANDON WELL TO DRILL DEEPER TO CHANGE PLANS Notice of Intention Notice of Intention . NOTICE OF INTENTION X TO SET LINER TO PLUG BACK TO PLUG WELL NOTICE OF INTENTION TO SHOOT (Nitro) Notice of Intention NOTICE OF INTENTION TO ACIDIZE TO SQUEEZE Notice of Intention NOTICE OF INTER NOTICE OF INTENTION TO GUN PERFORATE (OTHER) (OTHER) OIL CONSERVATION COMMISSION Farmington, New Mexico 25, 1957 SANTA FE, NEW MEXICO (Place) (Date) Gentlemen: Following is a Notice of Intention to do certain work as described below at the San Juan 27-4 Unit El Paso Natural Gas Company Well No. 14 (MD) in L (Company or Operator) East Companero Dakota Extension NMPM, Blanco Masa Verda Pools 18 .1/4 of Sec.... (40-acre Subdivision) Rio Arriba FULL DETAILS OF PROPOSED PLAN OF WORK (FOLLOW INSTRUCTIONS IN THE RULES AND REGULATIONS) Total depth of original hole 8008'. Original hole contains 1423' of dropped 5 1/2" casing and is squeezed off with 1075 sacks cement. Two subsequent attempts were made to drill

Total depth of original hole 8008'. Original hole contains 1423' of dropped 5 1/2" casing and is squeezed off with 1075 sacks cement. Two subsequent attempts were made to drill directional holes, failed, and were plugged with 550 and 1200 sacks of cement, respectively, Whipstock was set at 4086 and directional hole drilled to 6427', at which point water flow came in through hole in 9 5/8" casing at 3034-3039'. Water was shut off with 530 sack cement squeeze. The 9 5/8" casing is now partially collapsed at 3151-3154, with an 8 3/4" bit lost on bottom of directional hole at 6427'. Three attempts to recover the bit have failed. It is therefore intended to plug and abandon this well as follows:

- 1. Set east iron retainer in 9 5/8" casing at approximately 2950', and set 100 foot plug at bottom of casing from 3640 to 3540 with 40 sacks cement.
- 2. Set cement plug from 100' back to surface with 40 macks.

3. Set 4' x 4" pipe at surface as SEP 30 1957 , 19	
Except as follows:	Original Signed D. C. Johnston
Approved	Position Petroleum Engineer Send Communications regarding well to:
OIL CONSERVATION COMMISSION By Original Signed Emery C. Arnold	Name
Title Supervisor Dist. # 3	Address Box 997, Farmington, New Mexico

	•	
•		OIL CONSERVATION COMMISSION
		AZTEC DISTRICT OFFICE
		or transfer
		A Land
	•	
		Transporter /

.