Firm: 3160=5 November 1953 Formerly 9=0.51

## UNITED STATES UNITED STATES SUBMIT IN TRIPLICATE\* Other instructions on reverse side:

Form approved. Budget Bureau No. 1004-0138 Expires August 31 1985

6 IF INDIAN, ALLOTTEE OR TRIBE NAME

5. LEASE DESIGNATION AND SERIAL S SF 079364

	•			
JREAU OF L	AND M	MANAGEN	λΕΝΤ.	

INDDA	NOTICES	V ND	DEDODIC	$\cap$ N	WEI

The not use this form for proposals to drill or to deepen or plug back to a different reservoir.

Use "APPLICATION FOR PERMIT—" for such proposals.)

7. UNIT AGREEMENT NAME WELL X Rincon Unit OTHER NAME OF OPERATOR 8. FARM OR LEASE NAME Union Oil Company of California Rincon Unit 9. WBLL NO. ADDRESS OF OPERATOR 176 P. O. Box 2620 - Casper, WY 82602-2620 10. FIELD AND POOL OR WILDCAT

LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below)

990' FNL & 1180' FEL (NE NE)

11. SEC., T., B., M., OR BLE. AND SURVEY OR AREA Sec. 31, T27N, R6W

14 PERMIT NO 15 ELEVATIONS (Show whether DF, RT, GR. etc.)

API 30-039-82373

6649' GR

12. COUNTY OR PARISH: 13. STATE

NM Rio Arriba

Basin Dakota

16

## Check Appropriate Box To Indicase Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO SUBSEQUENT REPORT OF :

TEST WATER SHUT-OFF PCIC OR AUTER COSTS . WATER SHUT-OFF REPAIRING WELL FRANTURE TREAT PRACTURE TREATMENT ALTERING CARING SHOOT OR ACIDIZE SHOOTING OR ACIDIZING ABANDONMENT\* EPAIR WELL CHANCE DIASE

Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form. Other, Repair & Reactivate

SCRIBL PROPOSED OR CONFIGERATION. Clearly State all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally grissed, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

7733' TD: 7645' ETD

7374-80' Perfs: Graneros:

9-5/8" @ 318' w/210 sx d @ 7729' w/440 sx ent

7460-66', 7504-08' Dakota:

7515-21', 7542-48'

MAY1 1 1989

7670-88' (Sazd) Morrison:

OIL CON. DIV. DIST. 3

7545-461 Squeezed: 7464-65**′** 

7380-81'

The BLM Rincon Unit Well No. 176 last produced in December of 1987. requires that this well be repaired and returned to production or The casing will be tested, any leaks will be repaired, and the well will be returned to production.

Proposed Plan of Procedure Install blowdown line. N.U. and test Test anchors. MIRU pulling unit. Locate and Kill well with 2% KCl water. POOH with tubing.

Clean out to ±7645' PBTD. Run production squeeze hole in casing. Swab well in and release rig. tubing with packer at ±7300%

18. I hereby certify District Drilling TITLE SIGNED space for Federal or State office use) APPROVED BY CONDITIONS OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side

FARMINGTON RESOURCE AREA

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.