### UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

	otices and Reports on Wells		
1. Type of Well GAS	.7782723 (1. 1: (		SF-078103 If Indian, All. or
		No.	Tribe Name
2. Name of Operator		7.	Unit Agreement Nam
BURLINGTON RESOURCES			
RESOURCES 01	IL & GAS COMPANY	_	Huerfano Unit
3. Address & Phone No. of Ope	rator	8.	Well Name & Number Huerfano Unit #27
PO Box 4289, Farmington,		9.	API Well No. 30-045-05786
4. Location of Well, Footage,		10.	Field and Pool
790'FNL, 790'FEL, Sec. 23,	T-26-N, R-9-W, NMPM	11.	Ballard Pict.Cliff County and State San Juan Co, NM
	INDICATE NATURE OF NOTICE, RE		DATA
Type of Submission	Type of Action		-ma
_X_ Notice of Intent	Abandonment C		
Subsequent Report	Plugging Back No		
	Casing Repair Wa		
Final Abandonment	Altering Casing Co _X_ Other - Restimulate	onversion t	o Injection
.3. Describe Proposed or Co	mpleted Operations		
	mulate the Pictured Cliffs for following procedure:	rmation of	the subject well
2162'. Run open to surface w/150 Gilsonite, 0.4%	tubing. Clean out open hole thole logs. Run 3 1/2" casing sacks Class "B" 50/50 poz w/fluid loss, 3% Kcl. Perforate red Cliffs formation. Clean ou	to total de 2% gel, 0.3 , acidize a	pth. Cement casing % CFR-3, 5 pps and foam fracture
2162'. Run open to surface w/150 Gilsonite, 0.4%	hole logs. Run 3 1/2" casing D sacks Class "B" 50/50 poz w/ fluid loss, 3% Kcl. Perforate	to total de 2% gel, 0.3 , acidize a	epth. Cement casing & CFR-3, 5 pps and foam fracture on well to production
2162'. Run open to surface w/150 Gilsonite, 0.4%	hole logs. Run 3 1/2" casing D sacks Class "B" 50/50 poz w/ fluid loss, 3% Kcl. Perforate	to total de 2% gel, 0.3 e, acidize a at and retur	epth. Cement casing & CFR-3, 5 pps and foam fracture on well to production
2162'. Run open to surface w/150 Gilsonite, 0.4% treat the Pictur	hole logs. Run 3 1/2" casing D sacks Class "B" 50/50 poz w/ fluid loss, 3% Kcl. Perforate	to total de /2% gel, 0.3 c., acidize aut and retur	epth. Cement casing & CFR-3, 5 pps and foam fracture on well to production
2162'. Run open to surface w/150 Gilsonite, 0.4% treat the Pictur 14. I hereby certify that the Signed Character Character Signed Character Charac	hole logs. Run 3 1/2" casing sacks Class "B" 50/50 poz w/fluid loss, 3% Kcl. Perforate red Cliffs formation. Clean out	to total de /2% gel, 0.3 c, acidize a ct and retur (0)	epth. Cement casing & CFR-3, 5 pps and foam fracture on well to production
2162'. Run open to surface w/150 Gilsonite, 0.4% treat the Pictur	hole logs. Run 3 1/2" casing sacks Class "B" 50/50 poz w/fluid loss, 3% Kcl. Perforate red Cliffs formation. Clean out the foregoing is true and correct (MDWPC) Title Regulatory at ate Office use)	to total de /2% gel, 0.3 c, acidize a ct and retur (0)	epth. Cement casing & CFR-3, 5 pps and foam fracture on well to production

Meed To order @ NMOCD

# **Huerfano Unit #27 Pertinent Data Sheet**

API #: 300450578600

Location: 790 'FNL & 790 'FEL, Unit A, Section 23, T26N, R09W, San Juan County, New Mexico

Latitude: 36 ° - 28.72 '

**Longitude:** 107 ° - 45.12'

Field: Ballard PC

Elevation: 6353 GL

TD: 2062' PBTD: 2062

**6363** ' KB

**DP#:** 49376A

**Spud Date:** 8/27/54

**Compi Date:** 12/8/54

Lease: NM 6045-300 (Fed)

**GWI:** 62.55 %

Initial Potential = 1808 Mcfd

NRI: 45.35 %

Orig SIP = 643 psi

Prop#: 0-079711-00

### Casing Record:

Initial Potential:

Hole Size (In.)	Csg Size (In.)	Wt. (#'s) & Grade	Depth Set (Ft.)	Cement (Sx.)	Cement (Top)
12 1/4	8 5/8	22.7 Armco	118	75	circ to surf
7 7/8	5 1/2	14 J-55	2,012	75	1570' @ 75% eff.
4 3/4	openhole		2,012 -2,062		

#### **Tubing Record:**

Tbg. Size	Wt. & Grade	Depth Set	# Joints	Comments
1 1/4"	2.4 J-55 EUE	1,987	65	10' perf it on btm

#### Formation Tops:

Oio Alamo: 1,230'

Kirtland Shale: 1,329'

Fruitland:

1,824

Pictured Cliffs: 2,012'

#### Logging Record:

Original Stimulation: SOF w/ 4,000 gal oil and 4,000# sand

Workover History:

None

Production History: 7/97 PC capacity: 1.0 MCF/D. 7/97 PC cum: 1990.0 MMCF.

Pipeline:

**EPNG** 

# **Huerfano Unit #27**

Section 23 A, T-26-N R-09-W San Juan, New Mexico

## Ballard Pictured Cliffs Wellbore Schematic

