

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.
7. Unit Agreement Name
8. Farm or Lease Name Pound Ranch
9. Well No. 27
10. Field and Pool, or Wildcat
12. County Rio Arriba

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator Bedford, Inc. for Tamanaco Oil Corp. & State of New Mexico
3. Address of Operator P. O. Box E, Farmington, New Mexico 87401
4. Location of Well UNIT LETTER B 330 FEET FROM THE N LINE AND 1501 FEET FROM THE E LINE, SECTION 27 TOWNSHIP 28N RANGE 1 E NMPM.
15. Elevation (Show whether DF, RT, GR, etc.)

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

This well has been plugged & abandoned as follows:

10-16-78 Move in & Rig up  
10-17-78 Ran tbg. in hole, tag plug @ 854' Spot 11 sx plug on bottom  
10-18-78 Perf 4 holes @ 410' - Attempt to circulate. Perf. 4 holes @ 395' to 300'. Set P & A marker & clean location  
Cement IN + OUT



18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Larry A. Bedford</u>	TITLE <u>Agent for State</u>	DATE <u>10-26-78</u>
APPROVED BY <u>Al Kendrick</u>	TITLE <u>SUPERVISOR DIST. #3</u>	DATE <u>OCT 26 1978</u>
CONDITIONS OF APPROVAL, IF ANY:		