DEPARTMENT O	STATES F THE INTERI	SUBMIT IN TRIPLICAT (Other Instructions on verse side)	Form approved Budget Bureau No. 42-R14: 5. LEASE DESIGNATION AND BERIAL NO Contract # 241
SUNDRY NOTICES AN (Do not use this form for proposals to drill (Use "APPLICATION FOR)	or to deepen or nive b	and to a different or	6. IF INDIAN, ALLOTTER OR TRIBE NAM
OIL GAS WELL OTHER			7. UNIT AGREEMENT NAME
Tesoro Petroleum Corp.			8. FARM OR LEASE NAME Boulder
P. O. Box 23, Abilene, Texas 79604 LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* At surface			9. WELL NO. 9 10. FIELD AND FOOL, OR WILDCAT Boulder Plances
730' FSL & 2260' FEL Sec. 14, T28N R1W		11. SEC., T., R., M., OR BLK. AND BURVEY OR AREA	
	ONS (Show whether DF, $330~{ m KB}$	RT, GR, eta.)	Sec. 14, T28N R1W 12. COUNTY OR PARISH 13. STATS Rio Arriba New M
NOTICE OF INTENTION TO: TEST WATER SHUT-OFF PULL OR ALTE FRACTURE TREAT MULTIPLE COM	R CASING	ature of Notice, Report, or subse water shut-off fracture treatment	Other Data QUENT REPORT OF: REPAIRING WELL ALTERING CASING

SHOOT OR ACIDIZE

(This space for Federal or State

CONDITIONS OF APPROVAL, IF ANY:

APPROVED BY

REPAIR WELL

(Other)

ABANDON*

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting and proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and sones pertinent dates.

SHOOTING OR ACIDIZING

This well was reportedly shot with nitroglycerene while operated by Dr. Sam G. but never cleaned out. A 4 1/2" liner was originally set from 2738 to 3774, uncemented. On 21 Sep 72, after operations were assumed by Tesoro, we attempted to clean this well out and restore it to production. The liner was found parted and loose in the hole from 2378 to 3293, and was laid down. The hole was cleaned out to 3694 before running into iron in the hole, at which point operations were terminated. No oil, gas or water was produced from the well. This well is on inactive status pending results of proposed cleanout of other wells in the field.

> OIL CON. CON TITLE Project Engineer

No. 42-R1424. ND BBRIAL NO.

OR TRIBS NAME

ABANDONMENT*

Clean out

New Mexic