

LEASING NATIONAL OIL COMPANY
DUAL COMPLETION
Initial Packer Leakage Test

October 29, 1958

San Juan 28-7 Unit No. 73 (PM)

A

28-28-7

Rio Arriba

Mesa Verde and Pictured Cliffs

2760

Mesa Verde

September 26, 1958
Test Date

Pictured Cliffs

710

19

Pictured Cliffs

710

Mesa Verde

858

19

TIME MINUTES	MV PRESSURES PSIG	MV WORKING PRESSURES PSIG	(PC) SIP (C) PSIG	TEMP °F
15	360		713	68
30	350		713	70
45	340		713	70
60	329		713	71
130	299	Calc. 583	713	74
Mesa Verde		3699	5933	

D. K. Bryant

Pictured Cliffs

October 24, 1958
(Test Date)

Pictured Cliffs

806

47

Pictured Cliffs

806

Mesa Verde

930

28

TIME MINUTES	(PC) FLOWING PRESSURES PSIG	(PC) WORKING PRESSURES PSIG	(MV) SIP (T) PSIG	TEMP °F
15	263	283	930	60
30	171	180	930	61
45	139	140	930	62
60	113	116	930	63
120	79	80	930	65
180	65	67	930	63
Pictured Cliffs		920	927	

D. K. Bryant

The well is in good condition



No packer leakage in this well

The well is in good condition

H. L. Kendrick
Signed