

NEW MEXICO
OIL CONSERVATION COMMISSION
AZTEC, NEW MEXICO

June 6, 1957

El Paso Natural Gas Company
Box 997
Farmington, New Mexico

Att: Mr. E. J. Coel

Re: El Paso Natural Gas Company
#75 SJU 28-7, L-15-28N-7W

Dear Mr. Coel:

On June 4, 1957 packer leakage test was conducted on the above-named well. This test was witnessed by A. R. Kendrick of the Commission's Astec office. At the beginning of the test the casing pressure was 1051#, tubing pressure 1040#. The tubing was then flowed to the atmosphere for three hours. At the end of three hours the flowing tubing pressure was 269# and the shut-in casing pressure had dropped to 1034#, which is a 17# drop. During the flow period the temperature of the well had increased from 70° to 76°. The above information indicates that there is communication between the two zones.

As required by Oil Conservation Commission Rules and Regulations we are therefore directing that remedial action be instituted on the above well within the next 30 days.

Yours very truly

Emery C. Arnold
Supervisor, District #3

ARK:sks

cc: Mr. A. L. Porter
OCC, Santa Fe, N.M.

NEW MEXICO
OIL CONSERVATION COMMISSION
NEW MEXICO

June 2, 1938

Mr. J. H. ...
Box 227
Farmington, New Mexico

Dear Mr. ...:

Enclosed for you are ...
Yours very truly,

John H. ...

On June 1, 1938, a ... was conducted at the ... well. This test was ... of A. R. ... the ...
At the beginning of the test the casing pressure was 100%. The tubing was then flowed to the atmosphere for three hours. At the end of three hours the flowing tubing pressure was 100% and the shut-in casing pressure had dropped to 100%. During the ... the ... well had increased from 100% to 100%. The above information indicates that there is communication between the two zones.

As required by the Conservation Commission Rules and Regulations we are therefore reporting that remedial action is indicated on the above well within the next 15 days.

Very truly,

George W. ...
Inspector, District #

AKK:ks

cc: Mr. A. I. ...
Box 227, Santa Fe, N.M.